

AD-A106 445

BLACK AND VEATCH KANSAS CITY MO

NATIONAL DAM SAFETY PROGRAM. UNION LAKE DAM

DEC 80 E R BURTON, M L CALLAHAN

F/G 13/13


MISSOURI--ETC(U)

DACW43-80-C-0074

NL

UNCLASSIFIED

1 of 2  
AD-A106 445



**LEVEL II**

**MISSOURI-KANSAS CITY BASIN**

AL A 106445



**UNION LAKE DAM**

**JACKSON COUNTY, MISSOURI**

**MO 30225**

# **PHASE 1 INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM**

**DTIC FILE COPY**



**United States Army  
Corps of Engineers**  
... Serving the Army  
... Serving the Nation

**St. Louis District**

**DTIC  
ELECTE  
NOV 2 1981**  
**S D**

**PREPARED BY: U.S. ARMY ENGINEER DISTRICT. ST. LOUIS**

**FOR: STATE OF MISSOURI**

**DECEMBER 1980**

**81 10 26 067**

**DISTRIBUTION STATEMENT A**

**Approved for public release  
Distribution Unlimited**

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program Union Lake Dam (MO 30225) Jackson County, Missouri		5. TYPE OF REPORT & PERIOD COVERED Final Report
7. AUTHOR(s) Black & Veatch, Consulting Engineers		6. PERFORMING ORG. REPORT NUMBER
8. CONTRACT OR GRANT NUMBER(s) DACW43-80-C-0074		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS (12) 206
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSD-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		12. REPORT DATE December 1980
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSD-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		13. NUMBER OF PAGES Approximately 120
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) (10) Edwin R. /Burton Harry L. /Callahan		15. SECURITY CLASS. (of this report) UNCLASSIFIED
15a. DECLASSIFICATION/DOWNGRADING SCHEDULE		
16. DISTRIBUTION STATEMENT (of this Report) Approved for release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) (6) National Dam Safety Program. Union Lake Dam (MO 30225), Missouri - Kansas City Basin, Jackson County, Missouri. Phase I Inspection Report.		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety, Lake, Dam Inspection, Private Dams		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property.		

058350

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

## INSTRUCTIONS FOR PREPARATION OF REPORT DOCUMENTATION PAGE

**RESPONSIBILITY.** The controlling DoD office will be responsible for completion of the Report Documentation Page, DD Form 1473, in all technical reports prepared by or for DoD organizations.

**CLASSIFICATION.** Since this Report Documentation Page, DD Form 1473, is used in preparing announcements, bibliographies, and data banks, it should be unclassified if possible. If a classification is required, identify the classified items on the page by the appropriate symbol.

### COMPLETION GUIDE

**General.** Make Blocks 1, 4, 5, 6, 7, 11, 13, 15, and 16 agree with the corresponding information on the report cover. Leave Blocks 2 and 3 blank.

**Block 1.** Report Number. Enter the unique alphanumeric report number shown on the cover.

**Block 2.** Government Accession No. Leave Blank. This space is for use by the Defense Documentation Center.

**Block 3.** Recipient's Catalog Number. Leave blank. This space is for the use of the report recipient to assist in future retrieval of the document.

**Block 4.** Title and Subtitle. Enter the title in all capital letters exactly as it appears on the publication. Titles should be unclassified whenever possible. Write out the English equivalent for Greek letters and mathematical symbols in the title (see "Abstracting Scientific and Technical Reports of Defense-sponsored RDT/E," AD-667 000). If the report has a subtitle, this subtitle should follow the main title, be separated by a comma or semicolon if appropriate, and be initially capitalized. If a publication has a title in a foreign language, translate the title into English and follow the English translation with the title in the original language. Make every effort to simplify the title before publication.

**Block 5.** Type of Report and Period Covered. Indicate here whether report is interim, final, etc., and, if applicable, inclusive dates of period covered, such as the life of a contract covered in a final contractor report.

**Block 6.** Performing Organization Report Number. Only numbers other than the official report number shown in Block 1, such as series numbers for in-house reports or a contractor/grantee number assigned by him, will be placed in this space. If no such numbers are used, leave this space blank.

**Block 7.** Author(s). Include corresponding information from the report cover. Give the name(s) of the author(s) in conventional order (for example, John R. Doe or, if author prefers, J. Robert Doe). In addition, list the affiliation of an author if it differs from that of the performing organization.

**Block 8.** Contract or Grant Number(s). For a contractor or grantee report, enter the complete contract or grant number(s) under which the work reported was accomplished. Leave blank in in-house reports.

**Block 9.** Performing Organization Name and Address. For in-house reports enter the name and address, including office symbol, of the performing activity. For contractor or grantee reports enter the name and address of the contractor or grantee who prepared the report and identify the appropriate corporate division, school, laboratory, etc., of the author. List city, state, and ZIP Code.

**Block 10.** Program Element, Project, Task Area, and Work Unit Numbers. Enter here the number code from the applicable Department of Defense form, such as the DD Form 1498, "Research and Technology Work Unit Summary" or the DD Form 1634, "Research and Development Planning Summary," which identifies the program element, project, task area, and work unit or equivalent under which the work was authorized.

**Block 11.** Controlling Office Name and Address. Enter the full, official name and address, including office symbol, of the controlling office. (Equates to funding/sponsoring agency. For definition see DoD Directive 5200.20, "Distribution Statements on Technical Documents.")

**Block 12.** Report Date. Enter here the day, month, and year or month and year as shown on the cover.

**Block 13.** Number of Pages. Enter the total number of pages.

**Block 14.** Monitoring Agency Name and Address (if different from Controlling Office). For use when the controlling or funding office does not directly administer a project, contract, or grant, but delegates the administrative responsibility to another organization.

**Blocks 15 & 15a.** Security Classification of the Report: Declassification/Downgrading Schedule of the Report. Enter in 15 the highest classification of the report. If appropriate, enter in 15a the declassification/downgrading schedule of the report, using the abbreviations for declassification/downgrading schedules listed in paragraph 4-207 of DoD 5200.1-R.

**Block 16.** Distribution Statement of the Report. Insert here the applicable distribution statement of the report from DoD Directive 5200.20, "Distribution Statements on Technical Documents."

**Block 17.** Distribution Statement (of the abstract entered in Block 20, if different from the distribution statement of the report). Insert here the applicable distribution statement of the abstract from DoD Directive 5200.20, "Distribution Statements on Technical Documents."

**Block 18.** Supplementary Notes. Enter information not included elsewhere but useful, such as: Prepared in cooperation with ... Translation of (or by) ... Presented at conference of ... To be published in ...

**Block 19.** Key Words. Select terms or short phrases that identify the principal subjects covered in the report, and are sufficiently specific and precise to be used as index entries for cataloging, conforming to standard terminology. The DoD "Thesaurus of Engineering and Scientific Terms" (TEST), AD-672 000, can be helpful.

**Block 20.** Abstract. The abstract should be a brief (not to exceed 200 words) factual summary of the most significant information contained in the report. If possible, the abstract of a classified report should be unclassified and the abstract to an unclassified report should consist of publicly-releasable information. If the report contains a significant bibliography or literature survey, mention it here. For information on preparing abstracts see "Abstracting Scientific and Technical Reports of Defense-Sponsored RDT&E," AD-667 000.

# **MISSOURI-KANSAS CITY BASIN**

**UNION LAKE DAM**

**JACKSON COUNTY, MISSOURI**

**MO 30225**

## **PHASE 1 INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM**



**United States Army  
Corps of Engineers**

*Serving the Army  
Serving the Nation*

**St. Louis District**

**PREPARED BY: U.S. ARMY ENGINEER DISTRICT. ST. LOUIS**

**FOR: STATE OF MISSOURI**

**DECEMBER 1980**



DEPARTMENT OF THE ARMY  
ST. LOUIS DISTRICT, CORPS OF ENGINEERS  
210 TUCKER BOULEVARD, NORTH  
ST. LOUIS, MISSOURI 63101

REPLY TO  
ATTENTION OF

SUBJECT: Union Lake Dam, Mo. ID No. 30225  
Phase I Inspection Report

This report presents the results of field inspection and evaluation of the Union Lake Dam.

It was prepared under the National Program of Inspection of Non-Federal Dams.

This dam has been classified as unsafe, non-emergency by the St. Louis District as a result of the application of the following criteria:

- a. Spillway will not pass 50 percent of the Probable Maximum Flood without overtopping the dam.
- b. Overtopping of the dam could result in failure of the dam.
- c. Dam failure significantly increases the hazard to loss of life downstream.

SUBMITTED BY:

**SIGNED**

Chief, Engineering Division

**02 APR 1981**

Date

APPROVED BY :

**SIGNED**

Colonel, CE, District Engineer

**03 APR 1981**

Date

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or
A	Special

**DTIC**  
**ELECTE**  
**S NOV 2 1981 D**  
**D**

UNION LAKE DAM  
JACKSON COUNTY, MISSOURI

MISSOURI INVENTORY NO. 30225

PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM

PREPARED BY:

BLACK & VEATCH  
CONSULTING ENGINEERS  
KANSAS CITY, MISSOURI

UNDER DIRECTION OF  
ST. LOUIS DISTRICT CORPS OF ENGINEERS  
FOR  
GOVERNOR OF MISSOURI

DECEMBER 1980

PHASE I REPORT  
NATIONAL DAM SAFETY PROGRAM

Name of Dam	Union Lake Dam
State Located	Missouri
County Located	Jackson County
Stream	Tributary of Blue River
Date of Inspection	4 December 1980

Union Lake Dam was inspected by a team of engineers from Black & Veatch, Consulting Engineers for the St. Louis District, Corps of Engineers. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.

The guidelines used in the assessment were furnished by the Department of the Army, Office of the Chief of Engineers and developed with the help of several Federal and state agencies, professional engineering organizations, and private engineers. Based on these guidelines, this dam is classified as a small size dam with a high downstream hazard potential. According to the St. Louis District, Corps of Engineers, failure would threaten lives and property. The estimated damage zone extends approximately two miles downstream of the dam. Within the estimated damage zone are more than five dwellings, three roads, Interstate Hwy I-435, a railroad yard, and miscellaneous industrial facilities. Contents of the estimated downstream damage zone were verified by the inspection team.

Our inspection and evaluation indicates the spillways do not meet the criteria set forth in the guidelines for a dam having the above size and hazard potential. The spillways will not pass the probable maximum flood without overtopping but will pass 10 percent of the probable maximum flood. The spillways will not pass the flood which has a one percent chance of occurrence in any given year (100-year flood); but will pass the flood with a 10 percent chance of occurrence (10-year flood). The spillway design flood recommended by the guidelines is 50 to 100 percent of the probable maximum flood. Considering the damage zone, the spillway design flood should be 100 percent of the probable maximum flood. The probable maximum flood is defined as the flood discharge which may be expected from the most severe combination of critical meteorologic and hydrologic conditions which are reasonably possible in the region.

Based on visual observations, this dam appears to be in less than satisfactory condition. Deficiencies visually observed by the inspection

n



team were dense tree and brush cover, extremely steep upstream and downstream slopes, erosion of the upstream slope at the waterline due to wave action, erosion of the downstream slope from surface runoff and/or overtopping, partially plugged flow conduit, disjointed and displaced primary spillway pipe sections, a small sink hole over the primary spillway pipe, spillway channel erosion, and small animal burrows in the embankment. Seepage and stability analyses required by the guidelines were not available.

There were no observed deficiencies or conditions existing at the time of the inspection which indicated an immediate safety hazard. Future corrective action and regular maintenance will be required to correct or control the described deficiencies. In addition, detailed seepage and stability analyses of the existing dam, as required by the guidelines, should be performed. A detailed report discussing each of these deficiencies is attached.


*Edwin R. Burton*

Edwin R. Burton, PE  
Missouri E-10137

*Harry L. Callahan*

Harry L. Callahan, Partner  
Black & Veatch

OVERVIEW OF DAM



PHASE I INSPECTION REPORT  
NATIONAL DAM SAFETY PROGRAM  
UNION LAKE DAM

TABLE OF CONTENTS

<u>Paragraph No.</u>	<u>Title</u>	<u>Page No.</u>
SECTION 1 - PROJECT INFORMATION		
1.1	General	1
1.2	Description of Project	1
1.3	Pertinent Data	3
SECTION 2 - ENGINEERING DATA		
2.1	Design	6
2.2	Construction	6
2.3	Operation	6
2.4	Geology	6
2.5	Evaluation	6
SECTION 3 - VISUAL INSPECTION		
3.1	Findings	7
3.2	Evaluation	9
SECTION 4 - OPERATIONAL PROCEDURES		
4.1	Procedures	10
4.2	Maintenance of Dam	10
4.3	Maintenance of Operating Facilities	10
4.4	Description of Any Warning System in Effect	10
4.5	Evaluation	10
SECTION 5 - HYDRAULIC/HYDROLOGIC		
5.1	Evaluation of Features	11
SECTION 6 - STRUCTURAL STABILITY		
6.1	Evaluation of Structural Stability	13
SECTION 7 - ASSESSMENT/REMEDIAL MEASURES		
7.1	Dam Assessment	14
7.2	Remedial Measures	14

### LIST OF PLATES

<u>Plate No.</u>	<u>Title</u>
1	Location Map
2	Vicinity Topography
3	Dam Plan
4	Dam Crest Profile and Dam Cross Section
5	Photo Index

### LIST OF PHOTOGRAPHS

<u>Photo No.</u>	<u>Title</u>
1	Upstream Face of Dam Looking West
2	Upstream Face of Dam Looking East
3	Upstream Face of Dam, Left Center
4	Crest of Dam Looking West
5	Crest of Dam Looking East
6	Downstream Face of Dam Looking West
7	Downstream Face of Dam Looking East
8	Inlet End of Secondary Spillway Pipes, Right End of Dam
9	Outlet End of Concrete Pipe, Right End of Dam
10	Outlet End of Corrugated Metal Pipe, Right End of Dam
11	Channel Downstream of Corrugated Metal Pipe, Right End of Dam
12	Inlet End of Primary Spillway Pipe at Left End of Dam
13	Sink Hole in Crest at Separated Joint in Primary Spillway Pipe

LIST OF PHOTOGRAPHS  
(Cont'd)

<u>Photo No.</u>	<u>Title</u>
14	View Through Primary Spillway Pipe from Downstream End
15	Outlet End of Primary Spillway Pipe at Left End of Dam
16	Channel Downstream of Primary Spillway Pipe
17	Erosion on Downstream Face of Dam, Right Center
18	Erosion on Downstream Face of Dam, Right Center
19	Test Pit on Downstream Embankment Slope, Toe
20	Erosion at Left Side Concrete Primary Spillway Headwall
21	Overview of Upper Lake and Dam
22	Valley Downstream of Dam

APPENDICES

Appendix A - Hydrologic and Hydraulic Analyses  
Appendix B - Boring Logs

## SECTION 1 - PROJECT INFORMATION

### 1.1 GENERAL

a. Authority. The National Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of safety inspection of dams throughout the United States. Pursuant to the above, the District Engineer of the St. Louis District, Corps of Engineers, directed that a safety inspection of the Union Lake Dam, formerly called Joe's Fishing Lake, be made.

b. Purpose of Inspection. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.

c. Evaluation Criteria. Criteria used to evaluate the dam were furnished by the Department of the Army, Office of the Chief of Engineers, in "Recommended Guidelines for Safety Inspection of Dams." These guidelines were developed with the help of several Federal agencies and many state agencies, professional engineering organizations, and private engineers.

### 1.2 DESCRIPTION OF PROJECT

#### a. Description of Dam and Appurtenances.

(1) The dam is an earth structure located in the valley of a tributary of the Blue River (see Plate 1). The watershed is an area of low hills with fairly steep terrain consisting of about 60 percent urban development, 30 percent timber and 10 percent grassland. Small single family houses are located on large lots on the periphery of the watershed. Immediately upstream of Union Lake's reservoir pool is a small earthen dam and pool. The Union Lake dam is approximately 305 feet long along the crest and 27 feet high. The dam crest is 10 feet wide and is on a curved alinement. The downstream face of the dam has a nonuniform slope from the crest to the valley floor below.

(2) The spillway facilities for this dam consists of three conduits of different diameters. The primary conduit is a 30-inch concrete pipe located near the left abutment which discharges to an eroded channel. The inlet of this spillway includes a 22.6 feet long, 5.3 feet high concrete headwall.

Located near the right abutment are two conduits which also serve as points of discharge for this reservoir. One, a 12-inch diameter concrete pipe is partially plugged with earth, and the second is a 16-inch diameter corrugated metal pipe. Both pipes discharge to an eroded

channel on the right abutment. There is no headwall for these pipes, but there is a small trash screen a short distance upstream from these inlets.

(3) Located immediately upstream of Union Lake is a small earth dam. This dam has an 18-inch diameter corrugated metal pipe conduit spillway located near the right abutment. The dam has a worn gravel road across its crest.

(4) Pertinent physical data are given in paragraph 1.3.

b. Location. The dam is located in northeast Jackson County, Kansas City, Missouri, as indicated on Plate 1. The lake formed by the dam is shown on the United States Geological Survey 7.5 minute series quadrangle map for Independence, Missouri in Section 17 of T49N, R32W.

c. Size Classification. Criteria for determining the size classification of dams and impoundments are presented in the guidelines referenced in paragraph 1.1c above. Based on these criteria, the dam and impoundment are in the small size category. A small size dam is classified as having a height less than 40 feet, but greater than or equal to 25 feet and/or a storage capacity less than 1,000 acre-feet, but greater than or equal to 50 acre-feet.

d. Hazard Classification. The hazard classification assigned by the Corps of Engineers for this dam is as follows: The Union Lake Dam has a high hazard potential, meaning that the dam is located where failure may cause loss of life, and serious damage to homes, agricultural, industrial and commercial facilities, and to important public utilities, main highways, or railroads. For the Union Lake Dam the estimated flood damage zone extends approximately two miles downstream of the dam. Within the estimated damage zone are more than five dwellings, three roads, Interstate Hwy I-435, a railroad yard, and miscellaneous industrial facilities. Contents of the estimated downstream damage zone were verified by the inspection team.

e. Ownership. The dam is owned by the Sheet Metal Workers Local No. 2 (contact Mr. Foster), 101 E. Armour, Kansas City, Missouri 64111.

f. Purpose of Dam. The dam forms a 4.0-acre lake used for recreation.

g. Design and Construction History. Data relating to the design and construction were not available.

h. Normal Operating Procedure. Normal rainfall, runoff, transpiration, evaporation, and flow through the uncontrolled conduit spillways all combine to maintain a relatively stable water surface elevation.

### 1.3 PERTINENT DATA

a. Drainage Area - 61 acres, 30 acres uncontrolled.

b. Discharge at Damsite.

(1) Normal discharge at the damsite is through the three spillway conduits.

(2) Estimated experienced maximum flood at damsite - Unknown.

(3) Estimated ungated spillway capacity at maximum pool elevation 53 cfs (Probable Maximum Flood Pool El. 913.4).

c. Elevation (Feet above m.s.l., adjusted from Kansas City, Mo. datum).

(1) Top of dam - 911.6 (see Plate 3)

(2) Primary spillway pipe inlet invert - 909.2

(3) Secondary spillway pipe inlet inverts - 909.5 - 16 inch,  
910.4 - 12 inch

(4) Streambed at toe of dam - 884.3

(5) Maximum tailwater - Unknown.

d. Reservoir.

(1) Length of maximum pool - 520 feet  $\pm$  (Probable maximum flood pool level)

(2) Length of normal pool - 495 feet  $\pm$  (Primary spillway crest)

e. Storage (Acre-feet).

(1) Top of dam - 40

(2) Primary spillway inlet - 30

(3) Design surcharge - Not available.

f. Reservoir Surface (Acres).

(1) Top of dam - 4.4



(2) Primary spillway inlet - 4.0

g. Dam.

(1) Type - Earth embankment

(2) Length - 305 feet

(3) Height - 27 feet  $\pm$

(4) Top width - 10 feet

(5) Side slopes - upstream face 1.0 V on 1.8 H, downstream face between 1.0 V on 2.0 H and 1.0 V on 3.3 H (see Plate 4)

(6) Zoning - Unknown.

(7) Impervious core - Unknown.

(8) Cutoff - Unknown.

(9) Grout curtain - Unknown.

h. Diversion and Regulating Tunnel - None.

i. Primary Spillway.

(1) Type - Concrete pipe, 30-inch diameter.

(2) Inlet invert elevation - 909.2 feet m.s.l.

(3) Outlet invert elevation - 906.5 feet m.s.l.

(4) Gates - None.

(5) Upstream channel - None.

(6) Downstream channel - Discharges to an eroded channel leading to the natural stream below the dam.

j. Secondary Spillways.

A.

(1) Type - Concrete pipe, 12-inch diameter. (Blocked with earth)

(2) Inlet invert elevation - 910.4 feet m.s.l.

- (3) Outlet invert elevation - 909.0 feet m.s.l.
- (4) Gates - None.
- (5) Upstream channel - None.
- (6) Downstream channel - Discharges to an eroded channel leading to the natural stream below the dam.

B.

- (1) Type - Corrugated metal pipe, 16-inch diameter.
- (2) Inlet invert elevation - 909.5 feet m.s.l.
- (3) Outlet invert elevation - 909.1 feet m.s.l.
- (4) Gates - None.
- (5) Upstream channel - None.
- (6) Downstream channel - Discharges to an eroded channel leading to the natural stream below the dam.

k. Regulating Outlets - None.

## SECTION 2 - ENGINEERING DATA

### 2.1 DESIGN

Design data were not available.

### 2.2 CONSTRUCTION

Construction records were unavailable.

### 2.3 OPERATION

Operational records and documentation of past floods were unavailable. The watershed experienced a rainfall of about 12 inches in a 24-hour period in September 1977.

### 2.4 GEOLOGY

The dam is located across a shallow valley formed by a tributary to the Blue River. The soil of the dam and reservoir area consists of about 9 feet of low to medium plastic silty clay (CL for engineering purposes) developed in modified loess, overlying approximately 4 feet of highly plastic (CH for engineering purposes) residual clay underlain by the Chanute Shale. Bedrock of the general area consists of the Pennsylvanian age Kansas City Group. The formations consist of limestones and shales, with the Chanute Shale being the highest formation in the area, and the Block Limestone the lowest.

The foundation of the dam is on the Wea Shale with the Block Limestone present and outcropping in the middle dam area. The natural bottom of the lake is the Wea Shale with the Westerville Limestone cropping out along the shoreline. The left abutment consists of approximately 2 feet of low plastic silty clay (CL) over about 3 feet of highly plastic clay which overlies the Quivira Shale. The right abutment consists of the Quivira Shale.

### 2.5 EVALUATION

a. Availability. No engineering data were available.

b. Adequacy. No engineering data were available. Thus, an assessment of the design, construction, and operation could not be made. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading conditions (including earthquake loads) and made a matter of record.

c. Validity. The validity of the design, construction, and operation could not be determined due to the lack of engineering data.

## SECTION 3 - VISUAL INSPECTION

### 3.1 FINDINGS

a. General. A visual inspection of Union Lake Dam was made on 4 December 1980. The inspection team consisted of Edwin Burton, team leader; Shannon Casey, geologist; Gary Van Riessen, geotechnical engineer; Paul MacRoberts, civil engineer; Thomas L. Rutherford, hydrologic/hydraulic engineer; and Anthony C. Davis, civil engineer. The dam is in less than satisfactory condition. Specific observations are discussed below. No observations were made of the condition of the upstream face of the dam below the pool elevation at the time of the inspection.

b. Dam. The inspection team observed the following conditions at the dam. Conditions visually observed by the inspection team included dense tree and brush cover, steep upstream and downstream slopes, erosion of the upstream slope at the waterline due to wave action, erosion of the downstream slope due to surface runoff and apparent overtopping, partially plugged outlet conduit, spillway channel erosion, disjointed and displaced sections of the 30-inch discharge pipe, a small sink hole located over the 30-inch pipe, and small animal burrows. No cracking, sliding, sloughing or other signs of instability or settlement were observed.

The dam crest has a narrow gravel road surface with worn spots caused by apparent overtopping and vehicle/foot traffic. The upstream slope has visible remnants of slope protection, eg. railroad tie retainer wall, and riprap. These deteriorated features might possibly offer some localized protection from wave action. The downstream slope is covered with brush and trees. Trees range in size up to about 10-inches in diameter.

An apparently nonbackfilled inspection pit was observed at the toe of the dam about 50 feet from the right abutment. Some fairly well defined erosion gullies were observed on the downstream slope starting near the dam's crest. Gullies have also been formed at the discharge end of the spillway pipes.

Both the downstream and upstream slopes contain debris, such as cans, and discarded household appliances. The upstream and downstream slopes of the embankment are extremely steep. No instruments to measure the performance of the dam were located. No toe drains or relief wells were observed.

There was no evidence that a maintenance program was in effect. A few animal burrows and mole tunnels were observed on the downstream slope.

c. Appurtenant Structures. The inspection team observed the following items pertaining to the appurtenant structures. The primary spillway is a 30-inch concrete pipe which discharges into a channel cut in the left abutment. There was evidence of erosion in the spillway channel downstream of the pipe. The spillway was considered to be in poor condition. Open and displaced joints observed in the primary spillway pipe are potential locations for internal erosion of the embankment to occur. This is a probable cause of an observed sink hole over the pipe (Photo 13). It should be noted that an abnormally large spillway discharge is likely to damage the embankment due to open joints in the pipes. The secondary spillways, 12-inch concrete pipe (blocked with dirt and debris) and 16-inch corrugated metal pipe located near the right abutment discharge to an eroded channel.

There was no development in the spillway areas which would suffer damage due to flow through the spillways.

d. Geology. The soils in the area of the dam and reservoir consist of low to medium plastic silty clays developed in modified loess. Depth to bedrock, which is interbedded limestone and shale is approximately 13 to 17 feet on the uplands.

The embankment itself consists of stiff, medium to highly plastic (CL to CH) clays.

The abutments are Quivira Shale overlain on the left abutment by 5 feet of low to highly plastic clays, and the foundation of the dam is the Wea Shale, with the Block Limestone present and outcropping in the middle dam area.

Samples of the embankment were taken near the center of the upstream crest using an Oakfield sampler. The materials in the samples consisted of stiff, medium to highly plastic (CL to CH) clays. Based on these samples and visual observations, it is surmised that the embankment consists of silty, sandy clay classified as (CL).

e. Reservoir Area. No slumping or slides of the reservoir banks were observed. The upstream end of lake contains some minor debris and a few trees. The lake was noted to be clean with little or no siltation.

Located immediately upstream of the Union Lake is a small earthen dam. This dam is approximately 240 feet long along the crest. The dam crest is approximately 8 feet wide and has a straight alinement. The elevation at the top of the dam is 926.5 and the dam has a storage volume of 9 ac-ft. No inspection was made except to determine the hydraulic parameters to perform the breaching analysis.

f. Downstream Channel. Each spillway discharges to an eroded channel, then to the natural streambed. The channel immediately downstream of the dam is lined with brush and trees and contains debris.

### 3.2 EVALUATION

The various deficiencies observed at the time of the inspection are not believed to represent an immediate safety hazard. They do, however, warrant monitoring and control.

The potential for sloughing, erosion, or sliding of embankment material is enhanced by the presence of the relatively steep side slopes and the narrow crest.

The growth of trees and brush, if allowed to go unchecked, could cause deterioration of the embankment. The roots of trees can loosen the embankment material and also can leave voids through which water can pass. Brush on the dam prevents inspection of the embankment and kills the smaller grasses whose roots are more effective in protecting the surface soil of the slope from erosion. The brush provides habitat for burrowing animals which can damage the embankment.

The erosion gullies on the downstream face of the embankment should be repaired.

The absence of adequate riprap and slope protection on the upstream slope of the dam has resulted in wave action erosion. If not corrected wave action will continue to erode the embankment and could lead to slope stability problems.

Open and displaced joints observed in the 30-inch primary spillway pipe are areas where potential internal erosion can occur. If this deficiency is not corrected, internal erosion and piping will continue to take place and could lead to spillway and embankment failure.

Burrowing animals will continue to damage the embankment if a program is not undertaken to eliminate them. Piping failure of embankments have resulted from damage caused by burrowing animals.

## SECTION 4 - OPERATIONAL PROCEDURES

### 4.1 PROCEDURES

The pool is primarily controlled by rainfall, runoff, evaporation, transpiration, and capacity of the uncontrolled spillways.

### 4.2 MAINTENANCE OF DAM

There is no evidence that a maintenance program is in effect at this dam.

### 4.3 MAINTENANCE OF OPERATING FACILITIES

No operating facilities exist.

### 4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT

There is no existing warning system or preplanned scheme for alerting downstream residents for this dam.

### 4.5 EVALUATION

A maintenance program should be developed and initiated. A program should include mowing of the grass cover and controlling tree growth on the embankment in order to discourage animal burrowing and root penetration problems.

## SECTION 5 - HYDRAULIC/HYDROLOGIC

### 5.1 EVALUATION OF FEATURES

- a. Design Data. No design data were available.
- b. Experience Data. The drainage area and lake surface area are developed from USGS Independence Quadrangle Map. The dam layout and topographic maps were provided by the owner and developed by Shafer, Kline, and Warren P.A. of Overland Park, Kansas. These topographic maps were used to develop the storage-elevation curves.
- c. Visual Observations.
  - (1) The primary spillway appears to be in poor condition. The lake level at the time of the inspection (El. 907.3) was below the primary spillway inlet invert level. There were no obstructions to flow in the downstream channel.
  - (2) The secondary spillway conduits appear to be in less than fair condition. The lake level at the time of inspection was below their inlet elevations. The 12-inch concrete pipe spillway was essentially plugged with earth and debris and was not considered a discharge point for purposes of this report. The 16-inch corrugated metal pipe was open. The outlet ends of these pipes are located at an eroded channel at the right abutment.
  - (3) Spillway discharges do not endanger the integrity of the dam.
  - (4) Located immediately upstream from Union Lake's reservoir pool is a small earthen dam. This structure has an 18-inch corrugated metal pipe as its primary spillway.
- d. Overtopping Potential. The spillways will not pass the probable maximum flood without overtopping the dam. The probable maximum flood is defined as the flood discharge that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region. The spillways will pass 10 percent of the probable maximum flood without overtopping the dam. The spillways will not pass the one percent chance flood (100-year flood) developed from a 24-hour, one percent chance rainfall, but will pass the 10 percent chance flood (10-year flood) developed from a 24-hour, 10 percent chance rainfall. According to the recommended guidelines from the Department of the Army, Office of the Chief of Engineers, a high hazard dam of small size should pass 50 to 100 percent of the probable maximum flood. Considering the downstream hazard, the appropriate spillway design flood should be 100 percent of the probable maximum flood. The portion of the estimated peak discharge of 50 percent of the



probable maximum flood overtopping the dam would be 524 cfs of the total discharge from the reservoir of 571 cfs. The estimated duration of overtopping is 5.2 hours with a maximum height of 1.3 feet. The portion of the estimated peak discharge of the probable maximum flood overtopping the dam would be 1,142 cfs of the total discharge from the reservoir of 1,195 cfs. The estimated duration of overtopping is 7.3 hours with a maximum height of 1.8 feet. The embankment could be jeopardized should overtopping occur for these periods of time.

The hydraulic analysis for Union Lake includes the results of a breach analysis for the upstream impoundment.

According to the St. Louis District, Corps of Engineers, the effect from rupture of the dam could extend approximately two miles downstream of the dam. More than five dwellings, three roads, Interstate I-435, one railroad yard, and miscellaneous industrial facilities could be severely damaged and lives could be lost should failure of the dam occur. Contents of the estimated downstream damage zone were verified by the inspection team. Union Lake and its downstream damage zone are located in a Zone C (Area of Minimal Flooding) as defined by the National Flood Insurance Program. Applicable flood plain regulations and other constraints are in force as per the flood insurance study effective September 29, 1978.

## SECTION 6 - STRUCTURAL STABILITY

### 6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations. Visual observations of conditions which affect the structural stability of this dam are discussed in Section 3, paragraph 3.1b.

b. Design and Construction Data. No design data relating to the structural stability of the dam were found. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency.

c. Operating Records. No operational records exist.

d. Postconstruction Changes. It is not known whether or not any repairs have been made to the dam subsequent to its construction.

e. Rehabilitation: The owners of Union Lake have engaged the firm of Shafer, Kline, and Warren, P.A. to prepare engineering documents for the rehabilitation of the dam and appurtenances. An engineering report and construction drawings have been prepared. Subsurface explorations were performed in conjunction with the above engineering study. Boring logs obtained during this effort are presented in Appendix B.

f. Seismic Stability. The dam is located in Seismic Zone 1 which is a zone of *minor seismic risk*. A properly designed and constructed earth dam using sound engineering principles and conservatism should pose no serious stability problems during earthquakes in this zone. The seismic stability of an earth dam is dependent upon a number of factors: embankment and foundation material classifications and shear strengths; abutment materials, conditions, and strengths; embankment zoning; and embankment geometry. Adequate descriptions of embankment design parameters, foundation and abutment conditions, or static stability analyses to assess the seismic stability of this embankment were not available and therefore no inferences will be made regarding the seismic stability. An assessment of the seismic stability should be included as part of the stability analysis required by the guidelines.

## SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

### 7.1 DAM ASSESSMENT

a. Safety. Several conditions observed during the visual inspection by the inspection team should be monitored, controlled, and/or repaired. These are erosion on the downstream slope, extremely steep upstream and downstream slopes, erosion of upstream slope due to wave action, partially plugged spillway conduit, disjointed and displaced pipe sections, small sinkhole over the primary spillway pipe, spillway channels erosion, the dense growth of brush, and trees on the embankment, and animal burrows in the embankment. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency.

b. Adequacy of Information. Due to the absence of engineering design data, the conclusions in this report were based only on performance history and visual conditions. The inspection team considers that these data are sufficient to support the conclusions herein. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency.

c. Urgency. It is the opinion of the inspection team that a program should be developed as soon as possible to implement remedial measures recommended in paragraph 7.2b. If the safety deficiencies listed in paragraph 7.1a are not corrected, they will continue to deteriorate and lead to a serious potential of failure. The item recommended in paragraph 7.2a should be pursued on a high priority basis.

d. Necessity for Phase II. The Phase I investigation does not raise any serious enough questions relating to the safety of the dam nor does it identify any serious dangers which would require a Phase II investigation. However, the additional analyses noted in paragraph 2.5b are necessary for compliance with the guidelines.

e. Seismic Stability. This dam is located in Seismic Zone 1. Adequate description of embankment design parameters, foundation and abutment conditions, or static stability analyses to assess the seismic stability of this embankment were not available and therefore no inferences will be made regarding the seismic stability. An assessment of the seismic stability should be included as part of the recommended stability analysis.

### 7.2 REMEDIAL MEASURES

a. Alternatives. The condition of the primary spillway is a serious deficiency and it should be either repaired or replaced. In

addition, the spillway size and/or height of the dam would need to be increased or the lake level would need to be permanently lowered to increase available flood storage to effectively pass the spillway design flood.

b. Operation and Maintenance Procedures. The following operation and maintenance procedures are recommended and should be carried out under the direction of a professional engineer experienced in the design, construction, and maintenance of earth dams.

(1) Riprap should be placed on the upstream face of the dam to an elevation above the normal lake level to prevent wave induced erosion of the embankment material. The upstream slope should be cleared of all debris prior to placement of riprap.

(2) A maintenance program to remove and control the growth of brush and trees on the embankment should be developed. Grass/weed cover on the embankments should be cut periodically.

(3) The erosion gullies on the downstream slope of the embankment and the spillway channels should be repaired and protected with suitable materials. Paved ditches or other slope protection may be required to control the concentrated discharge from the spillways.

(4) The animal burrows in the embankment should be corrected since they can lead to piping. Control measures should be implemented to discourage this type of animal activity. The embankment slope should be monitored by a qualified engineer during the repair of the embankment.

(5) All debris and trash discarded on this structure and plugging in the secondary 12-inch diameter concrete pipe should be removed. Such accumulations not only give the appearance of poor maintenance but also can possibly hide potential problem areas.

(6) Seepage and stability analyses should be performed.

(7) A detailed inspection of the dam should be made periodically. More frequent inspections may be required if additional deficiencies are observed or the severity of the reported deficiencies increase.

(8) The inlet ends of the spillway pipes should have suitable trash racks installed.





PLATE I



# PLATE 2






PLATE 3



CREST PROFILE



NOTE:  
CROSS SECTION TAKEN  
NEAR STATION 1+60

CROSS SECTION

UNION LAKE DAM  
DAM CREST PROFILE  
DAM CROSS SECTION



# LEGEND

① PHOTO NUMBER  
& DIRECTION





PHOTO 21: VIEW OF UPPER LAKE AND DAM  
LOOKING DOWNSTREAM.

PHOTO 22: STREAM AND ROAD CROSSING  
APPROXIMATELY 0.7 MILES  
DOWNSTREAM OF DAM.



## UNION LAKE DAM PHOTO INDEX



PHOTO 1: UPSTREAM FACE OF DAM LOOKING WEST



PHOTO 2: UPSTREAM FACE OF DAM LOOKING EAST



PHOTO 3: UPSTREAM FACE OF DAM, LEFT CENTER



PHOTO 4: CREST OF DAM LOOKING WEST



PHOTO 5: CREST OF DAM LOOKING EAST



PHOTO 6: DOWNSTREAM FACE OF DAM LOOKING WEST



PHOTO 7: DOWNSTREAM FACE OF DAM LOOKING EAST




PHOTO 8: INLET END OF SECONDARY SPILLWAY PIPES, RIGHT END OF DAM




PHOTO 9: OUTLET END OF CONCRETE PIPE, RIGHT END OF DAM



PHOTO 10: OUTLET END OF CORRUGATED METAL PIPE, RIGHT END OF DAM




PHOTO 11: CHANNEL DOWNSTREAM OF CORRUGATED METAL PIPE,  
RIGHT END OF DAM



PHOTO 12: INLET END OF PRIMARY SPILLWAY PIPE AT LEFT END OF DAM



PHOTO 13: SINK HOLE IN CREST AT SEPARATED JOINT IN PRIMARY SPILLWAY  
PIPE




PHOTO 14: VIEW THROUGH PRIMARY SPILLWAY PIPE FROM DOWNSTREAM END





PHOTO 15: OUTLET END OF PRIMARY SPILLWAY PIPE AT LEFT END OF DAM



PHOTO 16: CHANNEL DOWNSTREAM OF PRIMARY SPILLWAY PIPE



PHOTO 17: EROSION ON DOWNSTREAM FACE OF DAM, RIGHT CENTER



PHOTO 18: EROSION ON DOWNSTREAM FACE OF DAM, RIGHT CENTER




PHOTO 19: TEST PIT ON DOWNSTREAM EMBANKMENT SLOPE, TOE




PHOTO 20: EROSION AT LEFT SIDE CONCRETE PRIMARY SPILLWAY HEADWALL



PHOTO 21: OVERVIEW OF UPPER LAKE AND DAM



PHOTO 22: VALLEY DOWNSTREAM OF DAM

APPENDIX A  
HYDROLOGIC AND HYDRAULIC ANALYSES

## HYDROLOGIC AND HYDRAULIC ANALYSES

To determine the overtopping potential, flood routings were performed by applying the Probable Maximum Precipitation (PMP) to synthetic unit hydrographs to develop the inflow hydrographs for Union Lake Dam and the upstream reservoir. The inflow hydrographs were then routed through the reservoirs and spillways. The overtopping analysis was determined using the computer program HEC-1 (Dam Safety Version) (1).

The PMP was determined from regional charts prepared by the National Weather Service in "Hydrometeorological Report No. 33" (HMR-33) (2). Reduction factors were not applied. The rainfall distribution for the 24-hour PMP storm was determined according to the procedures outlined in HMR-33 and EM 1110-2-1411 (3). The Kansas City, Missouri rainfall distribution (5 min. interval - 24 hours duration), as provided by the St. Louis District, Corps of Engineers, was used when the one and 10 percent chance probability floods were routed through the reservoirs and spillways.

The synthetic unit hydrographs for the watersheds were developed by the computer program using the Soil Conservation Service (SCS) method (1, 5). The parameters for the unit hydrographs are shown in Table 1. Lag time and time of concentration was calculated by two different methods. The results used in the analyses was obtained by using the Kerpich formula.

The SCS curve number (CN) method was used in computing the infiltration losses for rainfall-runoff relationship. The CN values used and the result from the computer output are shown in Table 2.

Storms were routed through the two reservoirs noted above. Routing through the reservoirs was performed using the modified Puls Method. The initial reservoir pool elevations for the routing of each storm were determined to be equivalent to the invert elevations of the primary spillways in accordance with antecedent storm conditions AMC II and AMC III preceding the one and ten percent probability and probable maximum storms as outlined by the U.S. Army Corps of Engineers, St. Louis District (4). The hydraulic capacity of the spillways and the storage capacities of the reservoirs were defined by the elevation, surface area, storage, and discharge relationships shown in Table 3.

The rating curves for the spillways are shown in Table 4. The flow over the crests of the dams was determined using the nonlevel dam crest option (\$L and \$V cards) of the HEC-1 program. The program assumes critical flow over a broad-crested weir. The flow through the primary and secondary spillways was determined from nomographs for pipe culverts with inlet control. The 12-inch diameter secondary spillway in the lower lake was blocked with dirt and debris and was not used in the analysis.

Where routings through the upstream reservoir resulted in overtopping of that structure, a breach analysis was performed using HEC-1. The breaching parameters are noted in Table 5.

The results of the routing and breach analyses indicate that a flood equivalent to a maximum of 10 percent of the PMF will not overtop Union Lake Dam.

A summary of the routing analysis for different ratios of the PMF is shown in Table 6.

The computer input data and a summary of the output data are presented at the back of this appendix.

TABLE 1  
SYNTHETIC UNIT HYDROGRAPH

<u>Parameters:</u>	Upper Dam	Lower Dam**
Drainage Area (A)	31 acres	30 acres
Lag Time ( $L_g$ )	0.085 hours	0.09 hours
Time of Concentration ( $T_c$ )	0.14 hours	0.15 hours
Duration (D)	5 minutes	5 minutes

Unit Hydrograph Ordinates  
Discharge (cfs)\*

<u>Time (Min.)*</u>	Upper Dam	Lower Dam
0	0	0
5	139	120
10	156	152
15	54	58
20	19	21
25	6	8
30	2	3
35	1	1

\* From HEC-1 Computer Output.

\*\* Excludes Controlled Drainage Area Upstream.

FORMULAS USED:

$$T_c = (11.9 L^3/H)^{0.385}$$

$$L_g = 0.6 T_c$$

$$D = 0.133 T_c$$



TABLE 2  
RAINFALL-RUNOFF VALUES

<u>Selected Storm Event</u>	<u>Storm Duration (Hours)</u>	<u>Rainfall (Inches)</u>	<u>Runoff (Inches)</u>	<u>Loss (Inches)</u>
Upper Dam PMP	24	32.50	30.01	2.49
Lower Dam PMP	24	32.50	30.01	2.49
Upper Dam 100 yr.	24	7.59	3.57	4.02
Lower Dam 100 yr.	24	7.59	3.57	4.02

Additional Data:

- 1) 100 Percent of Drainage Area in Hydrologic Soil Group B(7).  
60 Percent of the Land Use was Urban.  
30 Percent of the Land Use was Timberland.  
10 Percent of the Land Use was Grassland.
- 2) SCS Runoff Curve CN = 82 (AMC III) Lower Lake Dam  
82 (AMC III) Upper Lake Dam  
for the PMF (5).
- 3) SCS Runoff Curve CN = 65 (AMC II) Lower Lake Dam  
65 (AMC II) Upper Lake Dam  
for the one and 10 percent probability floods (5).

TABLE 3

ELEVATION, SURFACE AREA, STORAGE, AND DISCHARGE RELATIONSHIPS

<u>Elevation (feet-MSL)</u>	<u>Lake Surface Area (acres)</u>	<u>Lake Storage (acre-ft)</u>	<u>Spillway Discharge (cfs)</u>
Lower Lake Dam			
*909.2	4	30	0
**909.5	4	31	0
***911.6	4.4	40	30
Upper Lake Dam			
*922.3	1	4	0
**926.5	1.3	9	13

\*Primary spillway invert elevation

\*\*Secondary spillway invert elevation

\*\*\*Top of dam elevation

The relationships in Table 3 were developed from the Independence, Missouri. 7.5 minute quadrangle map, field measurements, and engineering documents provided by Shafer, Kline, and Warren, P.A.

TABLE 4  
SPILLWAY RATING CURVES

<u>Reservoir Elevation (ft-msl)</u>	<u>Primary Spillway Discharge (cfs)</u>	<u>Secondary Spillway Discharge (cfs)</u>	<u>Total Spillway Discharge (cfs)</u>
Lower Lake Dam			
*909.2	0	0	0
909.5	0	0	0
910.3	11.3	4.3	15.6
**911.6	24	7.3	30.0
914	49	11	60
916	61	14	75
Upper Lake Dam			
*922.3	0	-	0
924.0	6.8	-	6.8
**926.5	13.2	-	13.2
927.0	14.5	-	14.5
929.0	18.0	-	18.0
931.0	20.0	-	20.0

\*Primary Spillway Invert Elevation

\*\*Top of Dam Elevation

METHOD USED:

Primary and Secondary Spillway Release Rates are based on Nomographs for a Pipe Culvert with Inlet Control (6).

TABLE 5  
BREACHING PARAMETERS

	Upper Dam
Bottom Width of Breach (BRWID)	10 feet
Side Slope of Breach (z) (In feet horizontal to 1.0 feet vertical)	0.5
Elevation of Breach Bottom at Maximum Size of Breach (ELBM)	913.5 ft. m.s.l.
Time for Breach to Develop to Maximum Size (TFAIL)	1.0 hour
Elevation of Water Surface Which Will Cause Dam to Fail (FAILEL)	926.5 ft. m.s.l.

TABLE 6  
RESULTS OF FLOOD ROUTINGS

Ratio of PMF	Peak Inflow (CFS)	Peak Lake Elevation (ft.-MSL)	Total Storage (AC.-FT.)	Peak Outflow (CFS)	Depth (ft.) Over Top of Dam
-	0	*909.2	30	0	-
0.10	73	910.5	35	17	0
0.15	226	912.3	43	174	0.7
0.50	658	912.9	46	571	1.3
1.00	1,302	913.4	48	1,195	1.8

\* Primary Spillway Inlet Elevation

## BIBLIOGRAPHY

- (1) U.S. Army Corps of Engineers, Hydrologic Engineering Center, Flood Hydrograph Package (HEC-1), Dam Safety Version, July 1978, Modification April 1980, Davis, California.
- (2) HMR 33, Seasonal Variations of Probable Maximum Precipitation, East of the 105th Meridian for Areas 10 to 1000 Square Miles and Durations from 6 to 48 Hours, U.S. Department of Commerce, NOAA, National Weather Service, 1956.
- (3) EM-1110-2-1411, Standard Project Flood Determinations, U.S. Army Corps of Engineers, 26 March 1952.
- (4) U.S. Army Corps of Engineers, St. Louis District, Hydrologic/Hydraulic Standards, Phase I Safety Inspection of Non-Federal Dams, 22 August 1980.
- (5) U.S. Department of Agriculture, Soil Conservation Service, National Engineering Handbook, Section 4, Hydrology, August 1972.
- (6) U.S. Department of Commerce, Bureau of Public Roads, Hydraulic Charts For The Selection Of Highway Culverts, December 1965.
- (7) Mid-America Regional Council, Regional Soils Guide for Kansas City Area, March 1976.

U.S. Department of the Interior Bureau of Reclamation, Design of Small Dams, 1974, Washington, D.C.

Shafer, Kline and Warren, P.A., Design Report for Union Lakes Kansas City, Missouri.

Boring Logs from Woodward-Clyde Consultants, Summary of Laboratory Test Data, November 8, 1979.

National Flood Insurance Program, City of Kansas City, Missouri, U.S. Department of Housing and Urban Development, Community-Panel Number 2901730095A, September 29, 1978.





.....

ALL - NEW JERSEY  
 TO DIRECTOR, NEW JERSEY  
 FROM NEW JERSEY

[illegible]

WILLIAM-CLAY ANALYSES TO BE PERFORMED  
NPLAN=9 LPTIC=1

SUB-ARFA RUNOFF COMPUTATION

HYDROGRAPH FOR UPPER 6A"

ISTAGE	ICOMP	IECON	ISTAGE	JFLT	JPRY	ISAME	ISTAGE	IAUTO
1	0	0	0	0	0	1	0	0

HYDROGRAPH DATA			
JDATE	TSRPA	TSRDA	TRSCP
1950	00	00	00

RATIO			
ISNOW	ISAME	LOCAL	
0	0	0	

FTECIP DATA						
CODE	PWS	RO	R26	R48	R72	R96
000	25.00	101.00	120.00	110.00	.00	.00

[illegible]

09-28 = 103 157 144 = -1.00 = 55.26.34 = 0.1 14-113

UNIT HYDROGRAPH DATA  
TC# .20 PAGE .30

RECESSION DATA  
DATE 10/10/60  
LOCATION 1000

THE UNIVERSITY OF CHICAGO LIBRARY

[illegible]



DATE	TIME	PERIOD	RAIN	LOSS	END-OF-PERIOD FLOW	WQ-DA	HE-PM	PERIOD	RAIN	LOSS	CONP
12-01	1	12-05	145	21	19	41					
12-01	2	12-10	146	21	19	41					
12-01	3	12-15	147	21	19	41					
12-01	4	12-20	148	21	19	41					
12-01	5	12-25	149	21	19	41					
12-01	6	12-30	150	21	19	41					
12-01	7	12-35	151	21	19	41					
12-01	8	12-40	152	21	19	41					
12-01	9	12-45	153	21	19	41					
12-01	10	12-50	154	21	19	41					
12-01	11	12-55	155	21	19	41					
12-01	12	13-00	156	21	19	41					
12-01	13	13-05	157	21	19	41					
12-01	14	13-10	158	21	19	41					
12-01	15	13-15	159	21	19	41					
12-01	16	13-20	160	21	19	41					
12-01	17	13-25	161	21	19	41					
12-01	18	13-30	162	21	19	41					
12-01	19	13-35	163	21	19	41					
12-01	20	13-40	164	21	19	41					
12-01	21	13-45	165	21	19	41					
12-01	22	13-50	166	21	19	41					
12-01	23	13-55	167	21	19	41					
12-01	24	14-00	168	21	19	41					
12-01	25	14-05	169	21	19	41					
12-01	26	14-10	170	21	19	41					
12-01	27	14-15	171	21	19	41					
12-01	28	14-20	172	21	19	41					
12-01	29	14-25	173	21	19	41					
12-01	30	14-30	174	21	19	41					
12-01	31	14-35	175	21	19	41					
12-01	32	14-40	176	21	19	41					
12-01	33	14-45	177	21	19	41					
12-01	34	14-50	178	21	19	41					
12-01	35	14-55	179	21	19	41					
12-01	36	15-00	180	21	19	41					
12-01	37	15-05	181	21	19	41					
12-01	38	15-10	182	21	19	41					
12-01	39	15-15	183	21	19	41					
12-01	40	15-20	184	21	19	41					
12-01	41	15-25	185	21	19	41					
12-01	42	15-30	186	21	19	41					
12-01	43	15-35	187	21	19	41					
12-01	44	15-40	188	21	19	41					
12-01	45	15-45	189	21	19	41					
12-01	46	15-50	190	21	19	41					
12-01	47	15-55	191	21	19	41					
12-01	48	16-00	192	21	19	41					
12-01	49	16-05	193	21	19	41					
12-01	50	16-10	194	21	19	41					
12-01	51	16-15	195	21	19	41					
12-01	52	16-20	196	21	19	41					
12-01	53	16-25	197	21	19	41					

[illegible][illegible]



1. "FOR PLAN 1. BY 10 6"

CLASS	NUMBER	24-HOUR	72-HOUR	TOTAL VOLUME
100	120	4	72	192
200	1	1	1	2
1,000	26,010	20,008	20,008	20,008
10,000	65,000	761,427	7,414,400	761,427
100,000	44	72	72	72
1,000,000	76	76	76	76

HYDROGRAPHIC SURVING

RECEIVED  
JAN 10 1964  
U.S. DEPT. OF JUSTICE  
FEDERAL BUREAU OF INVESTIGATION  
WASHINGTON, D.C.

ITEM	COUP	REF	STAGE	JFLY	JDDT	INAVE	ISTAGE	IBUTO
1	1	0	0	0	0	1	0	0
ROUTING DATA								

DECLASSIFICATION

```
***** PROJECT C687 ***** DATE 30 DEC 90 PAGE 9  
*****  
***** PROGRAM M21/2-1V TIME 16:20:12 CASE DEF *****
```

CLASS	AVG	IPES	ISAP	IOPT	IPPP	LSTR
0.0	0.0	1	1	0	0	0

CLASS	AVG	LAG	AMSR	X	ISK	STORA	ISORAY
0.0	0	0	0.00	0.000	0.000	0.000	-1

Account	1934	1935	1936	1937	1938	1939	1940	1941	1942	1943	1944	1945	1946	1947	1948	1949	1950	1951	1952	1953	1954	1955	1956	1957	1958	1959	1960	1961	1962	1963	1964	1965	1966	1967	1968	1969	1970	1971	1972	1973	1974	1975	1976	1977	1978	1979	1980	1981	1982	1983	1984	1985	1986	1987	1988	1989	1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099	2100	2101	2102	2103	2104	2105	2106	2107	2108	2109	2110	2111	2112	2113	2114	2115	2116	2117	2118	2119	2120	2121	2122	2123	2124	2125	2126	2127	2128	2129	2130	2131	2132	2133	2134	2135	2136	2137	2138	2139	2140	2141	2142	2143	2144	2145	2146	2147	2148	2149	2150	2151	2152	2153	2154	2155	2156	2157	2158	2159	2160	2161	2162	2163	2164	2165	2166	2167	2168	2169	2170	2171	2172	2173	2174	2175	2176	2177	2178	2179	2180	2181	2182	2183	2184	2185	2186	2187	2188	2189	2190	2191	2192	2193	2194	2195	2196	2197	2198	2199	2200	2201	2202	2203	2204	2205	2206	2207	2208	2209	2210	2211	2212	2213	2214	2215	2216	2217	2218	2219	2220	2221	2222	2223	2224	2225	2226	2227	2228	2229	2230	2231	2232	2233	2234	2235	2236	2237	2238	2239	2240	2241	2242	2243	2244	2245	2246	2247	2248	2249	2250	2251	2252	2253	2254	2255	2256	2257	2258	2259	2260	2261	2262	2263	2264	2265	2266	2267	2268	2269	2270	2271	2272	2273	2274	2275	2276	2277	2278	2279	2280	2281	2282	2283	2284	2285	2286	2287	2288	2289	2290	2291	2292	2293	2294	2295	2296	2297	2298	2299	2300	2301	2302	2303	2304	2305	2306	2307	2308	2309	2310	2311	2312	2313	2314	2315	2316	2317	2318	2319	2320	2321	2322	2323	2324	2325	2326	2327	2328	2329	2330	2331	2332	2333	2334	2335	2336	2337	2338	2339	2340	2341</
---------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	--------

[illegible][illegible][illegible]

TYPEL	DAVID
9205	DAVID
00	DAVID
0000	DAVID

Country	Year	Value	Unit
Canada	1970	157	100
United States	1970	228	250
United Kingdom	1970	920.0	930.0
France	1970	977.0	911.0

CARD		LAW DELACH DATA		PAYABLE	PAID
10.	.50	CLP	FALL	USD	926.50
			1.00	922.50	



[illegible][illegible][illegible]

1.01	17.15	211	.23	.02	.00	84.
1.01	17.40	212	.23	.02	.00	84.
1.01	17.45	213	.23	.02	.00	84.
1.01	17.50	214	.23	.02	.00	84.
1.01	17.55	215	.23	.02	.00	84.
1.01	18.00	216	.23	.02	.00	84.
1.01	18.05	217	.23	.02	.00	84.
1.01	18.10	218	.23	.02	.00	84.
1.01	18.15	219	.23	.02	.00	84.
1.01	18.20	220	.23	.02	.00	84.
1.01	18.25	221	.23	.02	.00	84.
1.01	18.30	222	.23	.02	.00	84.
1.01	18.35	223	.23	.02	.00	84.
1.01	18.40	224	.23	.02	.00	84.
1.01	18.45	225	.23	.02	.00	84.
1.01	18.50	226	.23	.02	.00	84.
1.01	18.55	227	.23	.02	.00	84.
1.01	19.00	228	.23	.02	.00	84.
1.01	19.05	229	.23	.02	.00	84.
1.01	19.10	230	.23	.02	.00	84.
1.01	19.15	231	.23	.02	.00	84.
1.01	19.20	232	.23	.02	.00	84.
1.01	19.25	233	.23	.02	.00	84.
1.01	19.30	234	.23	.02	.00	84.
1.01	19.35	235	.23	.02	.00	84.
1.01	19.40	236	.23	.02	.00	84.
1.01	19.45	237	.23	.02	.00	84.
1.01	19.50	238	.23	.02	.00	84.
1.01	19.55	239	.23	.02	.00	84.
1.01	20.00	240	.23	.02	.00	84.
1.01	20.05	241	.23	.02	.00	84.
1.01	20.10	242	.23	.02	.00	84.
1.01	20.15	243	.23	.02	.00	84.
1.01	20.20	244	.23	.02	.00	84.
1.01	20.25	245	.23	.02	.00	84.
1.01	20.30	246	.23	.02	.00	84.
1.01	20.35	247	.23	.02	.00	84.
1.01	20.40	248	.23	.02	.00	84.
1.01	20.45	249	.23	.02	.00	84.
1.01	20.50	250	.23	.02	.00	84.
1.01	20.55	251	.23	.02	.00	84.
1.01	21.00	252	.23	.02	.00	84.
1.01	21.05	253	.23	.02	.00	84.
1.01	21.10	254	.23	.02	.00	84.
1.01	21.15	255	.23	.02	.00	84.
1.01	21.20	256	.23	.02	.00	84.
1.01	21.25	257	.23	.02	.00	84.
1.01	21.30	258	.23	.02	.00	84.
1.01	21.35	259	.23	.02	.00	84.
1.01	21.40	260	.23	.02	.00	84.
1.01	21.45	261	.23	.02	.00	84.
1.01	21.50	262	.23	.02	.00	84.
1.01	21.55	263	.23	.02	.00	84.
1.01	22.00	264	.23	.02	.00	84.
1.01	22.05	265	.23	.02	.00	84.
1.01	22.10	266	.23	.02	.00	84.
1.01	22.15	267	.23	.02	.00	84.
1.01	22.20	268	.23	.02	.00	84.
1.01	22.25	269	.23	.02	.00	84.
1.01	22.30	270	.23	.02	.00	84.
1.01	22.35	271	.23	.02	.00	84.
1.01	22.40	272	.23	.02	.00	84.
1.01	22.45	273	.23	.02	.00	84.
1.01	22.50	274	.23	.02	.00	84.
1.01	22.55	275	.23	.02	.00	84.
1.01	23.00	276	.23	.02	.00	84.
1.01	23.05	277	.23	.02	.00	84.
1.01	23.10	278	.23	.02	.00	84.
1.01	23.15	279	.23	.02	.00	84.
1.01	23.20	280	.23	.02	.00	84.
1.01	23.25	281	.23	.02	.00	84.
1.01	23.30	282	.23	.02	.00	84.
1.01	23.35	283	.23	.02	.00	84.
1.01	23.40	284	.23	.02	.00	84.
1.01	23.45	285	.23	.02	.00	84.
1.01	23.50	286	.23	.02	.00	84.
1.01	23.55	287	.23	.02	.00	84.
1.01	24.00	288	.23	.02	.00	84.
1.01	24.05	289	.23	.02	.00	84.
1.01	24.10	290	.23	.02	.00	84.
1.01	24.15	291	.23	.02	.00	84.
1.01	24.20	292	.23	.02	.00	84.
1.01	24.25	293	.23	.02	.00	84.
1.01	24.30	294	.23	.02	.00	84.
1.01	24.35	295	.23	.02	.00	84.
1.01	24.40	296	.23	.02	.00	84.
1.01	24.45	297	.23	.02	.00	84.
1.01	24.50	298	.23	.02	.00	84.
1.01	24.55	299	.23	.02	.00	84.
1.01	25.00	300	.23	.02	.00	84.

PLAN 1 V E A T I O N  
FLOOD HYDROGRAPH PACKAGE - MICH-1

TIME	12.45	13.00	13.15	13.30	13.45	14.00	14.15	14.30	14.45	15.00	15.15	15.30	15.45	16.00	16.15	16.30	16.45	17.00	17.15	17.30	17.45	18.00	18.15	18.30	18.45	19.00	19.15	19.30	19.45	20.00	20.15	20.30	20.45	21.00	21.15	21.30	21.45	22.00	22.15	22.30	22.45	23.00	23.15	23.30	23.45	24.00	24.15	24.30	24.45	25.00	25.15	25.30	25.45	26.00	26.15	26.30	26.45	27.00	27.15	27.30	27.45	28.00	28.15	28.30	28.45	29.00	29.15	29.30	29.45	30.00	30.15	30.30	30.45	31.00	31.15	31.30	31.45	32.00	32.15	32.30	32.45	33.00	33.15	33.30	33.45	34.00	34.15	34.30	34.45	35.00	35.15	35.30	35.45	36.00	36.15	36.30	36.45	37.00	37.15	37.30	37.45	38.00	38.15	38.30	38.45	39.00	39.15	39.30	39.45	40.00	40.15	40.30	40.45	41.00	41.15	41.30	41.45	42.00	42.15	42.30	42.45	43.00	43.15	43.30	43.45	44.00	44.15	44.30	44.45	45.00	45.15	45.30	45.45	46.00	46.15	46.30	46.45	47.00	47.15	47.30	47.45	48.00	48.15	48.30	48.45	49.00	49.15	49.30	49.45	50.00	50.15	50.30	50.45	51.00	51.15	51.30	51.45	52.00	52.15	52.30	52.45	53.00	53.15	53.30	53.45	54.00	54.15	54.30	54.45	55.00	55.15	55.30	55.45	56.00	56.15	56.30	56.45	57.00	57.15	57.30	57.45	58.00	58.15	58.30	58.45	59.00	59.15	59.30	59.45	60.00	60.15	60.30	60.45	61.00	61.15	61.30	61.45	62.00	62.15	62.30	62.45	63.00	63.15	63.30	63.45	64.00	64.15	64.30	64.45	65.00	65.15	65.30	65.45	66.00	66.15	66.30	66.45	67.00	67.15	67.30	67.45	68.00	68.15	68.30	68.45	69.00	69.15	69.30	69.45	70.00	70.15	70.30	70.45	71.00	71.15	71.30	71.45	72.00	72.15	72.30	72.45	73.00	73.15	73.30	73.45	74.00	74.15	74.30	74.45	75.00	75.15	75.30	75.45	76.00	76.15	76.30	76.45	77.00	77.15	77.30	77.45	78.00	78.15	78.30	78.45	79.00	79.15	79.30	79.45	80.00	80.15	80.30	80.45	81.00	81.15	81.30	81.45	82.00	82.15	82.30	82.45	83.00	83.15	83.30	83.45	84.00	84.15	84.30	84.45	85.00	85.15	85.30	85.45	86.00	86.15	86.30	86.45	87.00	87.15	87.30	87.45	88.00	88.15	88.30	88.45	89.00	89.15	89.30	89.45	90.00	90.15	90.30	90.45	91.00	91.15	91.30	91.45	92.00	92.15	92.30	92.45	93.00	93.15	93.30	93.45	94.00	94.15	94.30	94.45	95.00	95.15	95.30	95.45	96.00	96.15	96.30	96.45	97.00	97.15	97.30	97.45	98.00	98.15	98.30	98.45	99.00	99.15	99.30	99.45	100.00	100.15	100.30	100.45	101.00	101.15	101.30	101.45	102.00	102.15	102.30	102.45	103.00	103.15	103.30	103.45	104.00	104.15	104.30	104.45	105.00	105.15	105.30	105.45	106.00	106.15	106.30	106.45	107.00	107.15	107.30	107.45	108.00	108.15	108.30	108.45	109.00	109.15	109.30	109.45	110.00	110.15	110.30	110.45	111.00	111.15	111.30	111.45	112.00	112.15	112.30	112.45	113.00	113.15	113.30	113.45	114.00	114.15	114.30	114.45	115.00	115.15	115.30	115.45	116.00	116.15	116.30	116.45	117.00	117.15	117.30	117.45	118.00	118.15	118.30	118.45	119.00	119.15	119.30	119.45	120.00	120.15	120.30	120.45	121.00	121.15	121.30	121.45	122.00	122.15	122.30	122.45	123.00	123.15	123.30	123.45	124.00	124.15	124.30	124.45	125.00	125.15	125.30	125.45	126.00	126.15	126.30	126.45	127.00	127.15	127.30	127.45	128.00	128.15	128.30	128.45	129.00	129.15	129.30	129.45	130.00	130.15	130.30	130.45	131.00	131.15	131.30	131.45	132.00	132.15	132.30	132.45	133.00	133.15	133.30	133.45	134.00	134.15	134.30	134.45	135.00	135.15	135.30	135.45	136.00	136.15	136.30	136.45	137.00	137.15	137.30	137.45	138.00	138.15	138.30	138.45	139.00	139.15	139.30	139.45	140.00	140.15	140.30	140.45	141.00	141.15	141.30	141.45	142.00	142.15	142.30	142.45	143.00	143.15	143.30	143.45	144.00	144.15	144.30	144.45	145.00	145.15	145.30	145.45	146.00	146.15	146.30	146.45	147.00	147.15	147.30	147.45	148.00	148.15	148.30	148.45	149.00	149.15	149.30	149.45	150.00	150.15	150.30	150.45	151.00	151.15	151.30	151.45	152.00	152.15	152.30	152.45	153.00	153.15	153.30	153.45	154.00	154.15	154.30	154.45	155.00	155.15	155.30	155.45	156.00	156.15	156.30	156.45	157.00	157.15	157.30	157.45	158.00	158.15	158.30	158.45	159.00	159.15	159.30	159.45	160.00	160.15	160.30	160.45	161.00	161.15	161.30	161.45	162.00	162.15	162.30	162.45	163.00	163.15	163.30	163.45	164.00	164.15	164.30	164.45	165.00	165.15	165.30	165.45	166.00	166.15	166.30	166.45	167.00	167.15	167.30	167.45	168.00	168.15	168.30	168.45	169.00	169.15	169.30	169.45	170.00	170.15	170.30	170.45	171.00	171.15	171.30	171.45	172.00	172.15	172.30	172.45	173.00	173.15	173.30	173.45	174.00	174.15	174.30	174.45	175.00	175.15	175.30	175.45	176.00	176.15	176.30	176.45	177.00	177.15	177.30	177.45	178.00	178.15	178.30	178.45	179.00	179.15	179.30	179.45	180.00	180.15	180.30	180.45	181.00	181.15	181.30	181.45	182.00	182.15	182.30	182.45	183.00	183.15	183.30	183.45	184.00	184.15	184.30	184.45	185.00	185.15	185.30	185.45	186.00	186.15	186.30	186.45	187.00	187.15	187.30	187.45	188.00	188.15	188.30	188.45	189.00	189.15	189.30	189.45	190.00	190.15	190.30	190.45	191.00	191.15	191.30	191.45	192.00	192.15	192.30	192.45	193.00	193.15	193.30	193.45	194.00	194.15	194.30	194.45	195.00	195.15	195.30	195.45	196.00	196.15	196.30	196.45	197.00	197.15	197.30	197.45	198.00	198.15	198.30	198.45	199.00	199.15	199.30	199.45	200.00	200.15	200.30	200.45	201.00	201.15	201.30	201.45	202.00	202.15	202.30	202.45	203.00	203.15	203.30	203.45	204.00	204.15	204.30	204.45	205.00	205.15	205.30	205.45	206.00	206.15	206.30	206.45	207.00	207.15	207.30	207.45	208.00	208.15	208.30	208.45	209.00	209.15	209.30	209.45	210.00	210.15	210.30	210.45	211.00	211.15	211.30	211.45	212.00	212.15	212.30	212.45	213.00	213.15	213.30	213.45	214.00	214.15	214.30	214.45	215.00	215.15	215.30	215.45	216.00	216.15	216.30	216.45	217.00	217.15	217.30	217.45	218.00	218.15	218.30	218.45	219.00	219.15	219.30	219.45	220.00	220.15	220.30	220.45	221.00	221.15	221.30	221.45	222.00	222.15	222.30	222.45	223.00	223.15	223.30	223.45	224.00	224.15	224.30	224.45	225.00	225.15	225.30	225.45	226.00	226.15	226.30	226.45	227.00	227.15	227.30	227.45	228.00	228.15	228.30	228.45	229.00	229.15	229.30	229.45	230.00	230.15	230.30	230.45	231.00	231.15	231.30	231.45	232.00	232.15	232.30	232.45	233.00	233.15	233.30	233.45	234.00	234.15	234.30	234.45	235.00	235.15	235.30	235.45	236.00	236.15	236.30	236.45	237.00	237.15	237.30	237.45	238.00	238.15	238.30	238.45	239.00	239.15	239.30	239.45	240.00	240.15	240.30	240.45	241.00	241.15	241.30	241.45	242.00	242.15	242.30	242.45	243.00	243.15	243.30	243.45	244.00	244.15	244.30	244.45	245.00	245.15	245.30	245.45	246.00	246.15	246.30	246.45	247.00	247.15	247.30	247.45	248.00	248.15	248.30	248.45	249.00	249.15	249.30	249.45	250.00	250.15	250.30	250.45	251.00	251.15	251.30	251.45	252.00	252.15	252.30	252.45	253.00	253.15	253.30	253.45	254.00	254.15	254.30	254.45	255.00	255.15	255.30	255.45	256.00	256.15	256.30	256.45	257.00	257.15	257.30	257.45	258.00	258.15	258.30	258.45	259.00	259.15	259.30	259.45	260.00	260.15	260.30	260.45	261.00	261.15	261.30	261.45	262.00	262.15	262.30	262.45	263.00	263.15	263.30	263.45	264.00	264.15	264.30	264.45	265.00	265.15	265.30	265.45	266.00	266.15	266.30	266.45	267.00	267.15	267.30	267.45	268.00	268.15	268.30	268.45	269.00	269.15	269.30	269.45	270.00	270.15	270.30	270.45	271.00	271.15	271.30	271.45	272.00	272.15	272.30	272.45	273.00	273.15	273.30	273.45	274.00	274.15	274.30	274.45	275.00	275.15	275.30	275.45	276.00	276.15	276.30	276.45	277.00	277.15	277.30	277.45	278.00	278.15	278.30	278.45	279.00	279.15	279.30	279.45	280.00	280.15	280.30	280.45	281.00	281.15	281.30	281.45	282.00	282.15	282.30	282.45	283.00	283.15	283.30	283.45	284.00	284.15	284.30	284.45	285.00	285.15	285.30	285.45	286.00	286.15	286.30	286.45	287.00	287.15	287.30	287.45	288.00	288.15	288.30	288.45	289.00	289.15	289.30	289.45	290.00	290.15	290.30	290.45	291.00	291.15	291.30	291.45	292.00	292.15	292.30	292.45	293.00	293.15	293.30	293.45	294.00	294.15	294.30	294.45	295.00	295.15	295.30	295.45	296.00	296.15	296.30	296.45	297.00	297.15	297.30	297.4
------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	-------



PEAK	6-M-CPD	2,6-M-CPD	7,8-M-CPD	TOTAL
1	2.0	2.0	70	22.00
2	1.0	7	2	9.7
3	1.0	1	2	4.2
4	1.0	1.0	2.0	4.0
5	1.0	1.0	2.0	4.0
6	1.0	1.0	2.0	4.0
7	1.0	1.0	2.0	4.0
8	1.0	1.0	2.0	4.0
9	1.0	1.0	2.0	4.0
10	1.0	1.0	2.0	4.0
11	1.0	1.0	2.0	4.0
12	1.0	1.0	2.0	4.0
13	1.0	1.0	2.0	4.0
14	1.0	1.0	2.0	4.0
15	1.0	1.0	2.0	4.0
16	1.0	1.0	2.0	4.0
17	1.0	1.0	2.0	4.0
18	1.0	1.0	2.0	4.0
19	1.0	1.0	2.0	4.0
20	1.0	1.0	2.0	4.0
21	1.0	1.0	2.0	4.0
22	1.0	1.0	2.0	4.0
23	1.0	1.0	2.0	4.0
24	1.0	1.0	2.0	4.0
25	1.0	1.0	2.0	4.0
26	1.0	1.0	2.0	4.0
27	1.0	1.0	2.0	4.0
28	1.0	1.0	2.0	4.0
29	1.0	1.0	2.0	4.0
30	1.0	1.0	2.0	4.0
31	1.0	1.0	2.0	4.0
32	1.0	1.0	2.0	4.0
33	1.0	1.0	2.0	4.0
34	1.0	1.0	2.0	4.0
35	1.0	1.0	2.0	4.0
36	1.0	1.0	2.0	4.0
37	1.0	1.0	2.0	4.0
38	1.0	1.0	2.0	4.0
39	1.0	1.0	2.0	4.0
40	1.0	1.0	2.0	4.0
41	1.0	1.0	2.0	4.0
42	1.0	1.0	2.0	4.0
43	1.0	1.0	2.0	4.0
44	1.0	1.0	2.0	4.0
45	1.0	1.0	2.0	4.0
46	1.0	1.0	2.0	4.0
47	1.0	1.0	2.0	4.0
48	1.0	1.0	2.0	4.0
49	1.0	1.0	2.0	4.0
50	1.0	1.0	2.0	4.0
51	1.0	1.0	2.0	4.0
52	1.0	1.0	2.0	4.0
53	1.0	1.0	2.0	4.0
54	1.0	1.0	2.0	4.0
55	1.0	1.0	2.0	4.0
56	1.0	1.0	2.0	4.0
57	1.0	1.0	2.0	4.0
58	1.0	1.0	2.0	4.0
59	1.0	1.0	2.0	4.0
60	1.0	1.0	2.0	4.0
61	1.0	1.0	2.0	4.0
62	1.0	1.0	2.0	4.0
63	1.0	1.0	2.0	4.0
64	1.0	1.0	2.0	4.0
65	1.0	1.0	2.0	4.0
66	1.0	1.0	2.0	4.0
67	1.0	1.0	2.0	4.0
68	1.0	1.0	2.0	4.0
69	1.0	1.0	2.0	4.0
70	1.0	1.0	2.0	4.0
71	1.0	1.0	2.0	4.0
72	1.0	1.0	2.0	4.0
73	1.0	1.0	2.0	4.0
74	1.0	1.0	2.0	4.0
75	1.0	1.0	2.0	4.0
76	1.0	1.0	2.0	4.0
77	1.0	1.0	2.0	4.0
78	1.0	1.0	2.0	4.0
79	1.0	1.0	2.0	4.0
80</				

.....

.....

.....

.....

.....

NY 37033 AFM 000114

ADJUTANT GENERAL'S OFFICE  
WASHINGTON, D.C.

ISTAT	ICOP	REC4	TRAF	SPLIT	JDDY	INAME	ISTAGE	IAUTO
5	1	0	0	0	0	1	0	0
ROUTING DATA								
5005	416	1	1	1001	1000	---	1517	---
5005	416	1	1	1001	1000	---	1517	---
5005	416	1	1	1001	1000	---	1517	---

2214

```

=====
FRJFCY 09457      DATE 30 DEC 80      PAGE 30
=====
FRJFCY 09457      AT-27C-10      TIME 14:20:10      CASE 001
=====

```

1	0	971	CDC	CC	Y	TSR	STRA	ISPRAT
5-1-68	JUL 15	G	CON.	.00		.00	-69.	-1

[illegible][illegible][illegible]

W. A. C. 327A

TOREL	CNO	EXPD	DA=UID
11.0	1.0	1.0	1.0

[illegible]

5. F.L.A.H. T, QAL. 7

SI-011630 M4735036AM 061310-10-6.1

2000

# Upper Dam

## SUMMARY OF EDA SAFETY ANALYSIS

PLAN 1	ELEVATION STATION OUTFLOW	INITIAL VALUE 922.10 7.0 0.0	SPILLWAY CHEST 922.10 4.0 0.0	TOP OF DAM 926.50 6.0 13.0
RATIO OF PM1	PERCENT OF MAXIMUM	PERCENT OF MAXIMUM	PERCENT OF MAXIMUM	PERCENT OF MAXIMUM
1.0	100.0	100.0	100.0	100.0
0.9	90.0	90.0	90.0	90.0
0.8	80.0	80.0	80.0	80.0
0.7	70.0	70.0	70.0	70.0
0.6	60.0	60.0	60.0	60.0
0.5	50.0	50.0	50.0	50.0
0.4	40.0	40.0	40.0	40.0
0.3	30.0	30.0	30.0	30.0
0.2	20.0	20.0	20.0	20.0
0.1	10.0	10.0	10.0	10.0
0.0	0.0	0.0	0.0	0.0

PROJECT E9457 DATE 30 DEC 80 PAGE 70  
 GROUP AN M21/C2-1V TIME 14:26:17 CASE PFF

Lower Dam

SUMMARY OF DAM SAFETY ANALYSIS

RELATIVE ELEVATION FEET	INITIAL VALUE PROJECT FEET	SPILLWAY CREST FEET	TOP OF DAM FEET	TIME OF MAX CUTOFF HOURS	TIME OF FAILURE HOURS
100.00	100.00	100.00	100.00	10.00	10.00
95.00	95.00	95.00	95.00	10.00	10.00
90.00	90.00	90.00	90.00	10.00	10.00
85.00	85.00	85.00	85.00	10.00	10.00
80.00	80.00	80.00	80.00	10.00	10.00
75.00	75.00	75.00	75.00	10.00	10.00
70.00	70.00	70.00	70.00	10.00	10.00
65.00	65.00	65.00	65.00	10.00	10.00
60.00	60.00	60.00	60.00	10.00	10.00
55.00	55.00	55.00	55.00	10.00	10.00
50.00	50.00	50.00	50.00	10.00	10.00
45.00	45.00	45.00	45.00	10.00	10.00
40.00	40.00	40.00	40.00	10.00	10.00
35.00	35.00	35.00	35.00	10.00	10.00
30.00	30.00	30.00	30.00	10.00	10.00
25.00	25.00	25.00	25.00	10.00	10.00
20.00	20.00	20.00	20.00	10.00	10.00
15.00	15.00	15.00	15.00	10.00	10.00
10.00	10.00	10.00	10.00	10.00	10.00
5.00	5.00	5.00	5.00	10.00	10.00
0.00	0.00	0.00	0.00	10.00	10.00





```

P  A  C  W  R  V  F  A  T  C  M
LISTING OF INPUT DATA
IACRDRM 4271007-9
PAGE 1

```

[illegible][illegible]

SAS6, A SYSLIP-APP. FAC LAR, INC. 660200104000

WASG, R 3V58IP-UC7. -60200104200  
TAC LAUNING

GASG, A SYSLIP, M21. 040200004000  
FAC WADNINE

5450, T. 2.

650, 730.

526,740

5A56, 17.

6456, 1 10-

5A55.7 11.

Case, 11.

2AS6, T 14.

2456, 15.

2X01 575L1F.1027.007

1-20162M° 12M° 175A5 4° 10K2

PLACER JETLUM  
FLORE HYDROGRAPH PAGE -

104-76) 07:01:55 JALL AL-26/1+ 499080  
-----  
104 6: NAF 2 JALV 4:35, 138000







```
*****  
GLACR C V E R T C M          PROJECT 06457      DATE *2 JAN 84   PAGE  6  
*****  
RELION MFC/COMP/SP/PSIO - YES-    PROGRAM M2102-1V   TIME  09:13:40  
*****
```

BLACK RIVER TCM  
FLOOD HYDROGRAPH PACKAGE - MEC-1

PROJECT 05457  
PROGRAM 421/22-IV

DATE 02 JAN 84  
TIME 09:05:56

1.01	7.00	85	0.1	0.0	0.1	1.01	19.75	259	0.1	0.0	0.1
1.01	7.10	86	0.1	0.0	0.1	1.01	19.75	270	0.1	0.0	0.1
1.01	7.15	87	0.1	0.0	0.1	1.01	19.75	281	0.1	0.0	0.1
1.01	7.20	88	0.1	0.0	0.1	1.01	19.75	292	0.1	0.0	0.1
1.01	7.25	89	0.1	0.0	0.1	1.01	19.75	303	0.1	0.0	0.1
1.01	7.30	90	0.1	0.0	0.1	1.01	19.75	314	0.1	0.0	0.1
1.01	7.35	91	0.1	0.0	0.1	1.01	19.75	325	0.1	0.0	0.1
1.01	7.40	92	0.1	0.0	0.1	1.01	19.75	336	0.1	0.0	0.1
1.01	7.45	93	0.1	0.0	0.1	1.01	19.75	347	0.1	0.0	0.1
1.01	7.50	94	0.1	0.0	0.1	1.01	19.75	358	0.1	0.0	0.1
1.01	7.55	95	0.1	0.0	0.1	1.01	19.75	369	0.1	0.0	0.1
1.01	7.60	96	0.1	0.0	0.1	1.01	19.75	380	0.1	0.0	0.1
1.01	7.65	97	0.1	0.0	0.1	1.01	19.75	391	0.1	0.0	0.1
1.01	7.70	98	0.1	0.0	0.1	1.01	19.75	402	0.1	0.0	0.1
1.01	7.75	99	0.1	0.0	0.1	1.01	19.75	413	0.1	0.0	0.1
1.01	7.80	100	0.1	0.0	0.1	1.01	19.75	424	0.1	0.0	0.1
1.01	7.85	101	0.1	0.0	0.1	1.01	19.75	435	0.1	0.0	0.1
1.01	7.90	102	0.1	0.0	0.1	1.01	19.75	446	0.1	0.0	0.1
1.01	7.95	103	0.1	0.0	0.1	1.01	19.75	457	0.1	0.0	0.1
1.01	8.00	104	0.1	0.0	0.1	1.01	19.75	468	0.1	0.0	0.1
1.01	8.05	105	0.1	0.0	0.1	1.01	19.75	479	0.1	0.0	0.1
1.01	8.10	106	0.1	0.0	0.1	1.01	19.75	490	0.1	0.0	0.1
1.01	8.15	107	0.1	0.0	0.1	1.01	19.75	501	0.1	0.0	0.1
1.01	8.20	108	0.1	0.0	0.1	1.01	19.75	512	0.1	0.0	0.1
1.01	8.25	109	0.1	0.0	0.1	1.01	19.75	523	0.1	0.0	0.1
1.01	8.30	110	0.1	0.0	0.1	1.01	19.75	534	0.1	0.0	0.1
1.01	8.35	111	0.1	0.0	0.1	1.01	19.75	545	0.1	0.0	0.1
1.01	8.40	112	0.1	0.0	0.1	1.01	19.75	556	0.1	0.0	0.1
1.01	8.45	113	0.1	0.0	0.1	1.01	19.75	567	0.1	0.0	0.1
1.01	8.50	114	0.1	0.0	0.1	1.01	19.75	578	0.1	0.0	0.1
1.01	8.55	115	0.1	0.0	0.1	1.01	19.75	589	0.1	0.0	0.1
1.01	8.60	116	0.1	0.0	0.1	1.01	19.75	600	0.1	0.0	0.1
1.01	8.65	117	0.1	0.0	0.1	1.01	19.75	611	0.1	0.0	0.1
1.01	8.70	118	0.1	0.0	0.1	1.01	19.75	622	0.1	0.0	0.1
1.01	8.75	119	0.1	0.0	0.1	1.01	19.75	633	0.1	0.0	0.1
1.01	8.80	120	0.1	0.0	0.1	1.01	19.75	644	0.1	0.0	0.1
1.01	8.85	121	0.1	0.0	0.1	1.01	19.75	655	0.1	0.0	0.1
1.01	8.90	122	0.1	0.0	0.1	1.01	19.75	666	0.1	0.0	0.1
1.01	8.95	123	0.1	0.0	0.1	1.01	19.75	677	0.1	0.0	0.1
1.01	9.00	124	0.1	0.0	0.1	1.01	19.75	688	0.1	0.0	0.1
1.01	9.05	125	0.1	0.0	0.1	1.01	19.75	699	0.1	0.0	0.1
1.01	9.10	126	0.1	0.0	0.1	1.01	19.75	710	0.1	0.0	0.1
1.01	9.15	127	0.1	0.0	0.1	1.01	19.75	721	0.1	0.0	0.1
1.01	9.20	128	0.1	0.0	0.1	1.01	19.75	732	0.1	0.0	0.1
1.01	9.25	129	0.1	0.0	0.1	1.01	19.75	743	0.1	0.0	0.1
1.01	9.30	130	0.1	0.0	0.1	1.01	19.75	754	0.1	0.0	0.1
1.01	9.35	131	0.1	0.0	0.1	1.01	19.75	765	0.1	0.0	0.1
1.01	9.40	132	0.1	0.0	0.1	1.01	19.75	776	0.1	0.0	0.1
1.01	9.45	133	0.1	0.0	0.1	1.01	19.75	787	0.1	0.0	0.1
1.01	9.50	134	0.1	0.0	0.1	1.01	19.75	798	0.1	0.0	0.1
1.01	9.55	135	0.1	0.0	0.1	1.01	19.75	809	0.1	0.0	0.1
1.01	9.60	136	0.1	0.0	0.1	1.01	19.75	820	0.1	0.0	0.1
1.01	9.65	137	0.1	0.0	0.1	1.01	19.75	831	0.1	0.0	0.1
1.01	9.70	138	0.1	0.0	0.1	1.01	19.75	842	0.1	0.0	0.1
1.01	9.75	139	0.1	0.0	0.1	1.01	19.75	853	0.1	0.0	0.1
1.01	9.80	140	0.1	0.0	0.1	1.01	19.75	864	0.1	0.0	0.1

BLACK RIVER TCM  
FLOOD HYDROGRAPH PACKAGE - MEC-1

PROJECT 05457  
PROGRAM 421/22-IV

DATE 02 JAN 84  
TIME 09:05:56

1.01	11.45	121	1.0	0.5	1.0	1.01	21.40	284	0.1	0.0	0.1
------	-------	-----	-----	-----	-----	------	-------	-----	-----	-----	-----



BLACK & VEATCH  
FLOOD HYDROGRAPH PACKAGE - MEC-1

PROJECT 75657 DATE 12/02/83 PAGE 10  
PROGRAM W21/02-1V TYPE US3/06 CASE 444131X8

Upper Dam

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....

ELEVATION  
STORAGE  
OUTFLOW

INITIAL VALUE  
522.50  
5.  
0.

SPILLWAY CREST  
522.50  
5.  
0.

TOP OF DAM  
526.50  
5.  
11.

RATIO  
OF  
PPE

PARITYL  
RESERVOIR  
W.S. ELEV  
526.51

PARITYL  
STORAGE  
AC-FT  
5.

DURATION  
OVER TOP  
HOURS  
15.

TYPE OF  
PAR CUTFLOW  
HOURS  
15.73

TYPE OF  
FAILURE  
15.73

BLACK & VEATCH  
FLOOD HYDROGRAPH PACKAGE - MEC-1

PROJECT 75657 DATE 12/02/83 PAGE 10  
PROGRAM W21/02-1V TYPE US3/06 CASE 444131X8



APPENDIX B



BORING LOGS

## BORING LOG

### LEGEND AND NOMENCLATURE

Items shown on boring logs refer to the following:

1. Depth - Depth below reference elevation, ground surface unless otherwise shown.
2. Sample - Types designated by letter
  - D - Disturbed sample, obtained from auger cuttings or wash water for classification purposes only.
  - S - Split-Spoon sample, obtained by driving 2-inch split-spoon to determine penetration resistance and allow classification.
  - C - Liner tube sample, obtained by penetration of thick, wall sampler containing 2-inch diameter liner-tubes (California sampler).
  - U - Undisturbed sample, obtained by penetration of minimum 3 inch diameter, thin-wall tube using an open or, where indicated, fixed-piston sampling head.
- Rec - Recovery is expressed as a ratio of the length recovered to the total length pushed or driven (in inches) i.e.  $\frac{8}{12}$
- Resist - Resistance is designated as follows:
  - P - Sample pushed in one continuous movement by hydraulic rig action, maximum hydraulic pressure shown where pertinent.
  - <sup>36</sup><sub>9</sub> - Numbers indicate blows per 6 inches of sampler penetration when driven by a 140-pound hammer falling freely 30 inches. The Standard Penetration Resistance is the number of blows for the last 12 inches of penetration of the split-spoon sampler, e.g. 15. Note that a blow count can be given for the California sampler, but this is not the Standard Penetration Resistance.
3. Description - Description of material according to the Unified Soil Classification: word description gives soil constituents, consistency or density, and other appropriate classification characteristics. Unified Soil Classification symbols are shown on the USC column. Geologic names, where appropriate, are shown under Special Notes. A solid line indicates stratigraphic change; a dashed line indicates approximate location of stratigraphic change.
4. Special Notes and Field Observations - Pertinent observations made by Inspector during drilling including type of boring, free water level, water seepage, fluid loss, hole termination depth, etc.
5. Legend -

CFA - Continuous flight auger ATD - At time of drilling AD - After drilling DWL - Drill water loss DWR - Drill water return	 Water depth at specified time after drilling  Water entry depth at time
---	---

# BORING LOG

PROJECT NAME DAMS AND PONDS

B-1

PROJECT LOCATION 29th & Blue Ridge Cut Off

GEOLOGIST M. Robinette DRILLER R. Herber

SURFACE ELEVATION 244

ELEVATION DATUM City

SHEET 1 OF 2

PROJECT NO. K79-88

DATE 9-14-79

RIG CHE 55

WATER ENTERS None

Detected ATD

DEPTH	SAMPLE			DESCRIPTION	U.S.C.	SPECIAL NOTES AND FIELD OBSERVATIONS
	TYPE	REC	RESIST			
0				Stiff, dark brown, low plastic Silty CLAY	CL	Boring advanced with 4" diameter CFA  WC > PL
D				Very stiff, dark brown, medium plastic CLAY		
5						
10	D			Very stiff, dark brown, highly plastic CLAY	CH	
15						
D				SHALE: very stiff to hard, olive to buff, highly plastic, weathered	SH	
D				SHALE: very stiff to hard, maroon, highly plastic, weathered		
20				SHALE: very stiff to hard, olive to buff, highly plastic, clayey	SH	
25				LIMESTONE: light gray to light brown, fine grained, crystalline, slightly weathered	LS	

WOODWARD-CLYDE CONSULTANTS

FIGURE NO. 6



# BORING LOG

SHEET 2 OF 2

PROJECT NAME DAMS AND PONDS

PROJECT NO. K79-88

**B-1**

PROJECT LOCATION 29th & Blue Ridge Cut Off

DATE 9-14-79

RIG CME 55

WATER ENTERS None

SURFACE ELEVATION 244 ELEVATION DATUM City

Detected ATD[illegible]

**WOODWARD-CLYDE CONSULTANTS**

FIGURE NO. 7

# BORING LOG

SHEET 1 OF 1

PROJECT NAME DAMS AND PONDS

PROJECT NO. K79-88

**B-2**

PROJECT LOCATION 29th & Blue Ridge Cut Off

DATE 3-14-79

RIG CME 55

GEOLOGIST M. Robinette DRILLER R. Herber

WATER ENTERS None

SURFACE ELEVATION 240

ELEVATION DATUM City

**Detected ATD**

DEPTH	SAMPLE			DESCRIPTION	U.S.C.	SPECIAL NOTES AND FIELD OBSERVATIONS
	TYPE	REC	RESIST			
0				Stiff, dark brown, low plastic Silty CLAY	CL	Boring advanced with 4" diameter CFA  WC > PL
				Very stiff, dark brown, highly plastic CLAY	CH	
5						
10						
	D					
15						
	D			SHALE: very stiff to hard, olive to maroon, highly plastic	SH	
20						
				LIMESTONE: light gray to light brown, fine grained, crystalline, slightly weathered	LS	
25						Bottom of boring 22.5'

WOODWARD-CLYDE CONSULTANTS

FIGURE NO. 8

# BORING LOG

SHEET 1 OF 1

PROJECT NAME DAMS AND PONDS

PROJECT NO. K79-88

B-3

PROJECT LOCATION 29th & Blue Ridge Cut Off

DATE 9-14-79

GEOLOGIST M. Robinette DRILLER R. Herber

RIG CME 55

WATER ENTERS None

SURFACE ELEVATION 236

ELEVATION DATUM City

Detected ATD

DEPTH	SAMPLE			DESCRIPTION	U.S.C.	SPECIAL NOTES AND FIELD OBSERVATIONS
	TYPE	REC	RESIST			
0				Stiff, dark brown, medium plastic Silty CLAY		Boring advanced with 4" diameter CFA  WC > PL
				Becoming medium brown	CL	
5	D					
10	D			Very stiff, medium brown, highly plastic CLAY	CH	
15						
				LIMESTONE: light gray to light brown, fine grained, crystalline, slightly weathered	LS	
20						Bottom of boring 18.0'

WOODWARD-CLYDE CONSULTANTS

FIGURE NO. 9

# BORING LOG

PROJECT NAME DAMS AND PONDS

B-4

PROJECT LOCATION 29th & Blue Ridge Cut Off

GEOLOGIST M. Robinette DRILLER R. Herber

SURFACE ELEVATION 231

ELEVATION DATUM City

SHEET 1 OF 1

PROJECT NO. K79-88

DATE 9-14-79

RIG CME 55

WATER ENTERS None

Detected ATC

DEPTH	SAMPLE			DESCRIPTION	U.S.C.	SPECIAL NOTES AND FIELD OBSERVATIONS
	TYPE	REC	RESIST			
0				Stiff, dark brown to black, low plastic, Silty CLAY	CL	Boring advanced with 4" diameter CFA  WC > PL
				Stiff, medium brown, medium plastic Silty CLAY		
5	D					
10				Very stiff, dark brown, highly plastic CLAY	CH	Bottom of boring 17.0'
	D					
15				LIMESTONE: light gray to light brown, fine grained, crystalline, weathered to slightly weathered	LS	
20						

WOODWARD-CLYDE CONSULTANTS

FIGURE NO. 10

# BORING LOG

PROJECT NAME DAMS AND PONDS

B-5

PROJECT LOCATION 29th & Blue Ridge Cut Off

GEOLOGIST M. Robinette DRILLER R. Herber

SURFACE ELEVATION 226

ELEVATION DATUM City

SHEET 1 OF 1

PROJECT NO. K79-88

DATE 9-14-79

RIG CME 55

WATER ENTERS None

Detected ATD

DEPTH	SAMPLE			DESCRIPTION	U.S.C.	SPECIAL NOTES AND FIELD OBSERVATIONS
	TYPE	REC	RESIST			
0				Stiff, medium brown, highly plastic CLAY with trace of silt	CH	Boring advanced with 4" diameter CFA WC > PL
5	D					
10				Very stiff, dark brown, highly plastic CLAY with trace of silt		WC > PL
	D					
15				LIMESTONE: buff to red brown, medium grained, slightly to very weathered	LS	
				SHALE: very stiff to hard, mottled black and olive, highly plastic, clayey, weathered	SH	
	D					
20						Bottom of boring 19.0'

WOODWARD-CLYDE CONSULTANTS

FIGURE NO. 11

# BORING LOG

PROJECT NAME DAMS AND PONDS

SHEET 1 OF 1

PROJECT NO. K70-88

B-6

PROJECT LOCATION 29th & Blue Ridge Cut Off

DATE 9-14-70

GEOLOGIST M. Robinette DRILLER R. Herber

RIG CME 55

SURFACE ELEVATION 212

ELEVATION DATUM City

WATER ENTERS None

Detected ATD

DEPTH	SAMPLE			DESCRIPTION	U.S.C.	SPECIAL NOTES AND FIELD OBSERVATIONS
	TYPE	REC	RESIST			
0						
	D			Stiff, dark brown, highly plastic CLAY with trace of silt	CH	Boring advanced with 4" diameter CFA
5				LIMESTONE: highly weathered	LS	
	D			Stiff, dark brown, highly plastic CLAY with trace of silt	CH	
10				SHALE: very stiff, olive and light brown highly plastic, clayey, weathered	SH	
	D					
15				SHALE: hard, blue gray, highly plastic, slightly weathered to weathered		
	D					
20				LIMESTONE: buff to brown, medium grained weathered	LS	
	D			SHALE: hard, light gray, highly plastic, slightly weathered	SH	
	D			LIMESTONE	LS	
25						Bottom of boring 23.0'

WOODWARD-CLYDE CONSULTANTS

FIGURE NO. 12

# BORING LOG

PROJECT NAME DAMS AND PONDS

SHEET 1 OF 1

PROJECT NO. K79-88

B-7

PROJECT LOCATION 29th & Blue Ridge Cut Off

DATE 9-14-79

GEOLOGIST G. K. Hess DRILLER R. Herber

RIG CME 55

SURFACE ELEVATION 225

ELEVATION DATUM City

WATER ENTERS None

Detected ATD

DEPTH	SAMPLE			DESCRIPTION	U.S.C.	SPECIAL NOTES AND FIELD OBSERVATIONS
	TYPE	REC	RESIST			
0				Stiff, medium to light brown, low plastic Silty CLAY	CL	Boring advanced with 4" diameter CFA
5	D					WC < PL
10	D			Stiff, medium brown, highly plastic CLAY	CH	
15				LIMESTONE: gray to light brown, fine to medium grained, weathered	LS	
				SHALE: hard, tan to light green, highly plastic, weathered	SH	
20	D			SHALE: dark gray to black, highly plastic, slightly weathered		
				SHALE: medium to light gray, highly plastic, slightly to unweathered, with trace calcareous zones		
25						Bottom of boring 24.0'

WOODWARD-CLYDE CONSULTANTS

FIGURE NO. 13

# BORING LOG

PROJECT NAME DAMS AND PONDS

B-8

PROJECT LOCATION 29th & Blue Ridge Cut Off

GEOLOGIST G. K. Hess DRILLER R. Herber

WINFACE ELEVATION 223 ELEVATION DATUM City

SHEET 1 OF 1

PROJECT NO. K70-88

DATE 9-14-79

RIG CME 55

WATER ENTERS None

Detected ATD

DEPTH (1)	SAMPLE			DESCRIPTION	U.S.C.	SPECIAL NOTES AND FIELD OBSERVATIONS
	TYPE	REC	RESIST			
				Stiff, medium brown, low to medium plastic Silty CLAY	CL	Boring advanced with 4" diameter CFA WC < PL
5	D					WC > PL
10				LIMESTONE: light gray to light brown, fine to medium grained, weathered  Becoming slightly weathered	LS	
15				SHALE: dark gray to black, highly plastic, slightly weathered	SH	
						Bottom of boring 14.0'

WOODYARD-CLYDE CONSULTANTS

FIGURE NO. 14



# BORING LOG

PROJECT NAME DAMS AND PONDS

B-9

PROJECT LOCATION 29th & Blue Ridge Cut Off

GEOLOGIST G. K. Hess DRILLER R. Herber

SURFACE ELEVATION 237 ELEVATION DATUM City

SHEET 1 OF 1

PROJECT NO. K79-88

DATE 9-14-79

RIG CME 55

WATER ENTERS None

Detected ATD

DEPTH	SAMPLE			DESCRIPTION	U.S.C.	SPECIAL NOTES AND FIELD OBSERVATIONS
	TYPE	REC	RESIST			
0				Stiff to very stiff, medium brown, medium to low plastic Silty CLAY	CL	Boring Advanced with 4" diameter CFA WC > PL
5						
10						
15				Stiff, medium brown, highly plastic CLAY with trace of silt	CH	Bottom of boring 19.0'
				LIKSTONE: light gray to light brown, fine to medium grained, weathered	LS	
20				SHALE: very stiff, medium brown, highly plastic, weathered	SH	

WOODWARD-CLYDE CONSULTANTS

FIGURE NO. 15

# BORING LOG

PROJECT NAME DAMS AND PONDS

SHEET 1 OF 1

PROJECT NO. K79-88

B-10

PROJECT LOCATION 29th & Blue Ridge Cut Off

DATE 9-14-79

GEOLOGIST G. K. Hess DRILLER R. Herber

RIG CME 55

SURFACE ELEVATION 244

ELEVATION DATUM City

WATER ENTERS None

Detected ATD

DEPTH	SAMPLE			DESCRIPTION	U.S.C.	SPECIAL NOTES AND FIELD OBSERVATIONS
	TYPE	REC	RESIST			
0				Stiff, medium brown, medium to low plastic Silty CLAY	CL	Boring advanced with 4" diameter CFA
5	D					WC > PL
10	D					
15						
	D			Stiff, medium brown, highly plastic CLAY	CH	
				SHALE: very stiff to hard, maroon to medium brown, highly plastic, weathered	SH	
20				Becoming tan		
	D					
				LIMESTONE: light gray to light brown, fine to medium grained, weathered to slightly weathered	LS	
25						Bottom of boring 24.0'

WOODWARD-CLYDE CONSULTANTS

FIGURE NO. 16

# BORING LOG

SHEET 1 OF 1

PROJECT NAME DAMS AND PONDS

PROJECT NO. K79-88

B-11

PROJECT LOCATION 29th & Blue Ridge Cut Off

DATE 9-14-79

GEOLOGIST G. K. Hess DRILLER C. Meyer

RIG CHE 55

SURFACE ELEVATION 206

ELEVATION DATUM City

WATER ENTERS None

Detected ATD

DEPTH	SAMPLE			DESCRIPTION	U.S.C.	SPECIAL NOTES AND FIELD OBSERVATIONS
	TYPE	REC	RESIST			
0				Very stiff, medium brown, highly plastic, CLAY FILL with limestone and shale fragments	F I L L	Boring advanced with 4" diameter CFA  WC > PL
	C	4 TZ	P	Becoming predominantly shale		
5				Stiff, mottled dark brown, light brown and light green, highly plastic CLAY FILL with some silt and trace of shale fragments		
	C	7 TZ	P		CH	
	C	4 TZ	P	Stiff, gray to light green, highly plastic CLAY with limestone cobble at 8'		
10				Becoming stiff to very stiff		
	C	7 TZ	P		CH I SH	
	C	8 TZ	P	Very stiff, mottled gray and light brown, highly plastic CLAY with trace of silt		
15				Grading to highly plastic CLAY to weathered Clayey SHALE		
	C	4/6	P		LS	Bottom of boring 18.0'
20				LIMESTONE: light gray to light brown, fine to medium grained, slightly weathered		

WOODWARD-CLYDE CONSULTANTS

FIGURE NO. 17

# **BORING LOG**

PROJECT NAME DAMS AND PONDS

SHEET 1 OF 2

PROJECT NO. K79-88

DATE 9-14-79

RIG CHE 75

WATER ENTERS @ EI 183

**B-12**

PROJECT LOCATION 29th & Blue Ridge Cut Off

GEOLOGIST G. K. Hess DRILLER C. Meyer

SURFACE ELEVATION 205± ELEVATION DATUM City

ATD

DEPTH	SAMPLE			DESCRIPTION	U.S.C.	SPECIAL NOTES AND FIELD OBSERVATIONS
	TYPE	REC	RESIST			
0				Gravel Fill	F	Boring advanced with 4" diameter CFA
				Very stiff, dark brown, highly plastic CLAY FILL with trace limonite nodules and shale fragments	L	
	C	$\frac{4}{10}$	P			
5				With some low to medium plastic clay zones		
	C	$\frac{8}{12}$	P			
	U	$\frac{12}{12}$	P			
				Stiff, gray-green, highly plastic CLAY and SHALE FILL with silt		
	C	$\frac{7}{12}$	P			
10						
	U	$\frac{10}{12}$	P	Firm, mottled gray to light green, medium to highly plastic CLAY FILL with shale fragments		
15				Firm, mottled medium to dark brown, low plastic Silty CLAY	CL	
	U	$\frac{12}{12}$	P			
20				With occasional limestone fragments		
	U	$\frac{12}{12}$	P			
				SHALE: stiff to very stiff, medium gray, highly plastic, weathered	SH	← Water detected ATD
25						

WOODWARD-CLYDE CONSULTANTS

FIGURE NO. 18

# **BORING LOG**

SHEET 2 OF 2

PROJECT NO. K79-88

DATE 9-14-79

RIG CME 75

WATER ENTERS @ E1 183

ATD

PROJECT NAME DAMS AND PONDS

**B-12**

PROJECT LOCATION 29th & Blue Ridge Cut Off

GEOLOGIST G. K. Hess DRILLER C. Meyer

SURFACE ELEVATION 205± ELEVATION DATUM City

[illegible]

**WOODWARD-CLYDE CONSULTANTS**

FIGURE NO. 19

# BORING LOG

PROJECT NAME DAMS AND PONDS

SHEET 1 OF 1

PROJECT NO. K79-88

B-13

PROJECT LOCATION 29th & Blue Ridge Cut Off

DATE 9-14-79

GEOLOGIST G. K. Hess DRILLER C. Meyer

RIS CME 75

SURFACE ELEVATION 206

ELEVATION DATUM City

WATER ENTERS None

Detected ATD

DEPTH	SAMPLE			DESCRIPTION	U.S.C.	SPECIAL NOTES AND FIELD OBSERVATIONS
	TYPE	REC	RESIST			
0				Very stiff, medium brown, medium plastic, CLAY FILL with limestone and shale fragments	F I L L	Boring advanced with 4" diameter CFA
	C	0 T2	P			
				SHALE: stiff, mottled tan to light brown, highly plastic, very weathered	SH	
5	C	4 T2	P			
				With brown layers		
	C	6 T2	P			
				Becoming olive green		
10	C	4 T2	P			
				Becoming mottled gray and yellow brown with limestone fragments		
	C	6 T2	P			
15						
				Becoming gray and slightly weathered		
20						
						Bottom of boring 17.0'

WOODWARD-CLYDE CONSULTANTS

FIGURE NO. 20

# BORING LOG

SHEET 1 OF 2  
 PROJECT NO. K79-88  
 DATE 9-14-79  
 RIG CME 75  
 WATER ENTERS None  
 Detected ATD

PROJECT NAME DAMS AND PONDS

B-14

PROJECT LOCATION 29th & Blue Ridge Cut Off

GEOLOGIST G. V. Hess DRILLER C. Meyer

SURFACE ELEVATION 192

ELEVATION DATUM City

DEPTH	SAMPLE			DESCRIPTION	U.S.C.	SPECIAL NOTES AND FIELD OBSERVATIONS
	TYPE	REC	RESIST			
0				Very stiff, medium brown, medium plastic gravel and CLAY FILL	FILL	Boring advanced with 4" diameter CFA  WC < PL
				Very stiff, medium brown, highly plastic, desiccated CLAY FILL		
	C	$\frac{4}{12}$	P			
5	C	$\frac{8}{12}$	P	With some low plastic silty layers		WC > PL
	C	$\frac{4}{12}$	P			
10					CL	
	C	$\frac{8}{12}$	P	Stiff, dark gray to dark brown, low plastic Silty CLAY with trace of organic matter		
					CH	
	C	$\frac{6}{12}$	P	Stiff, mottled medium brown to gray, highly plastic CLAY with some silt		
15					SH	
				SHALE: hard, tan, highly plastic, weathered		
	C	$\frac{4}{8}$	P			
20						
				Becoming slightly weathered		
	C	$\frac{4}{4}$	P			
25						

WOODWARD-CLYDE CONSULTANTS

FIGURE NO. 21

# BORING LOG

SHEET 2 OF 2

PROJECT NAME DAMS AND PONDS

PROJECT NO. K79-88

8-14

PROJECT LOCATION 29th & Blue Ridge Cut Off

DATE 9-14-70

RIG CME 75

GEOLOGIST G. K. Hess DRILLER C. Meyer

WATER ENTERS None

SURFACE ELEVATION 192 ELEVATION DATUM City

detected ATD

[illegible]

WOODWARD-CLYDE CONSULTANTS

FIGURE NO. 22



# BORING LOG

PROJECT NAME DAMS AND PONDS

B-15

PROJECT LOCATION 29th & Blue Ridge Cut Off

GEOLOGIST G. K. Hess DRILLER R. Herber

SURFACE ELEVATION 189 ELEVATION DATUM City

SHEET 1 OF 2

PROJECT NO. K79-88

DATE 9-14-79

RIG CME 55

WATER INTERS None

Detected ATD

DEPTH	SAMPLE			DESCRIPTION	U.S.C.	SPECIAL NOTES AND FIELD OBSERVATIONS
	TYPE	REC	RES/ST			
0				Very stiff, medium to light brown, low plastic CLAY FILL with gravel	F I L L	Boring advanced with 4" diameter CFA  WC > PL
				Very stiff, medium brown, highly plastic CLAY FILL with some silt		
5	C	$\frac{10}{12}$	P	Becoming medium to highly plastic		
				Becoming very stiff and mottled with gray		
10	U	$\frac{18}{18}$	P	Becoming medium plastic		
15	C	$\frac{8}{12}$	P	Stiff, brown to gray green, medium plastic Silty CLAY FILL with a trace of organic matter		
20	U	$\frac{0}{12}$	P	Stiff, mottled light brown and medium brown, highly plastic CLAY FILL with trace of silt and some low plastic zones		
	U	$\frac{12}{12}$	P			
25						

WOODWARD-CLYDE CONSULTANTS

FIGURE NO. 23